

TOWNSHIP 26 RANGE 08 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4665)

Set a fir post, 3 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. mkd ¼ S on W face, from which

A fir, 12" dia., bears N.30°E., 15 lks., mkd: ¼ S BT.

A fir, 10" dia., bears N.25°W., 32 lks., mkd: ¼ S BT.

Triangle Engineering Co. Nick Juliano - May 1972 - M44-79 & C.S. File 55/251

Found - 24" Fir, (snag), N.30°E., 9.9 ft. Rotted Face.
28" Fir, (snag), N.25°W., 21.1 ft. Scribe visible.

Set - 1½" Iron pipe with brass Cap. Referenced with "W" nails and plates.

New BTs- 22" Fir, S.66°E., 9.5 ft.

30" Fir, N.57°W., 3.9 ft.

Note - Face of 24" BT in NE quadrant badly rotted. Small portion of smooth face and ax marks still visible.

Face of 28" BT in NW quadrant also badly rotted. However by chopping a hole in back of BT a small part of positive scribe is visible.