

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 11 & 14

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4668)

-----

Set fir post, 3 ft. long, 4" sq., 24" in the ground for 1/4 sec. cor. mkd 1/4 S on N face, from which  
A fir, 36" dia., bears N.55°W., 54 lks., mkd: 1/4 S BT.  
A hemlock, 8" dia., bears S.54°W., 33 lks., mkd: 1/4 S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - Sept. 1968 - C.S. File 54/72-21

-----

Found - Orig. 36", now 54" Fir, alive, N.55°W. 35.6 ft., opened, blaze pitched over.  
Orig. 8" Hemlock, now 16" shattered stump, S.54°W., 21.8 ft., find "1/4 S BT" scribe on pieces.

Set - Brass Cap at Cor. Mkd: County Surveyors T26S R8W  
Office 1/4 S 11  
1968 S 14

New BTs- 36" D.Fir S.38°E., 9.6 ft. mkd: "1/4 S14 CS BT".  
24" Hemlock N.8°E., 7.0 ft. mkd: "1/4 S11 CS BT".

This corner lies on moderate east slope 50 ft. W. of old logging road.

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 3/26/2026 - C.S. File 67/62-34

-----

Found - 2 1/2" DCSO brass cap projecting 16" (properly mkd)  
Sawn 60"x2 1/2' fir stump N.55°W., 35.5 ft. (dist. not checked)  
Sawn 38"x3' D.Fir stump S.38°E., 9.6 ft. fully healed single blaze.  
Very rotted 30"x2 1/2' Hemlock stump N.8°E., 7.0 ft. face loose from stump has all scribing.

New - 10" D.Fir N.11°W., 16.2 ft scribed "1/4 S11 BT" on double blaze, 3 1/2" mag nail right side center.  
18" D.Fir N.40°W., 11.3 ft. scribed "1/4 S11 BT" on double blaze, 3 1/2" mag nail right side center.  
20" D.Fir S.34°W., 25.2 ft. scribed "1/4 S14 BT" on double blaze, 3 1/2" mag nail right side center.

Note - Compass decl. 14 1/4°E.  
New gravel road is east 85 ft. and edge of fire break is south 40 ft.

Trimble GEO XT position:  
N 43°.31624974 W 123°.61460210