

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 1 & 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>GLO Survey by - A.R. & S.C. Flint, Under Contract #392, dated May 26, 1881 (DCSO records Vol. 11 Page(s) 4648)</p> <p>-----</p> <p>Set laurel post, for ¼ sec. cor. 3 ft long, 3" sq. from which A hemlock, 14" dia., bears S.80°W., 3 lks. A hemlock, 10" dia., bears N.25°W., 37 lks.</p>
<p>GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4661)</p> <p>-----</p> <p>Make diligent search but find no trace of the ¼ sec. cor.</p>
<p>Dependent resurvey by Peter A. Peterson & Daniel L. Berry, Cadastral Surveyors, under Group No. 739, surveyed May/July 1971 - (DCSO Records Vol. 37 Page(s) 15219-20)</p> <p>-----</p> <p>Point for the ¼ sec. cor. of secs. 1 & 12, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28 long, 2½" dia., 24" in the ground with brass cap marked:</p> <p style="text-align: center;">¼ $\frac{S \ 1}{S \ 12}$ T26S R8W 1971</p> <p>from which A fir, 6" dia., bears N.19½°W., 34 lks., mkd: ¼ S1 BT. A fir, 8" dia., bears S.60°E., 25 lks., mkd: ¼ S12 BT.</p>
<p>BLM Dependent resurvey by James E. Jelley & Wayne L Rogers, Cadastral Surveyor under Group #1128 surveyed Jan. 1983- (DCSO records Vol. 43 Page(s) 16757-8)</p> <p>-----</p> <p>Point for the ¼ sec. cor. of secs. 1 & 12, at midpoint in departure on the S bdy. of sec. 1; there is no remaining evidence of the original cor. From this point, the ¼ sec. cor. of secs. 1 & 12, erroneously established by Peterson & Berry in 1971, bears S.23°32'W., 0.20 chs. monumented with an iron post, 2½" dia., firmly set, protruding 4" above ground, with brass cap mkd. as described in the field notes of the resurvey. <u>Move the iron post to the corner point and</u> <u>Reset the iron post</u>, 28" long, 2½" dia., 24" in the ground, with brass cap mkd.</p> <p style="text-align: center;">¼ $\frac{S \ 1}{S \ 12}$ T26S R8W 1983 1971</p> <p>from which a BT mkd by Peterson & Berry</p>

cont next pg

TOWNSHIP 26 RANGE 08 POINT IDENTIFIER # 640600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 1 & 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A fir, 8" dia., bears S.20¼°E., 33 lks. with healed blaze. and a new BT
A fir, 6" dia., bears N.37¼°W., 50 lks., mkd: ¼ S1 BT. The NW tree mkd. in 1971 has been destroyed by logging activity.

Fd. & used on BLM Dependent resurvey by Wayne L Rogers, Cadastral Surveyor under Group #1382 surveyed May/Aug 1987- (DCSO records Vol. 48 Page(s) 18447)
Fd. Ok by G. Baughman, 8/1990 - M110-55
Fd. Ok 5/1999 - by E. Farr 1999-0103

Ken Hoffine - For: Lone Rock Timber Co - May, 1991- M 113-48

Found - 3" BLM brass cap/iron pipe 0.3 ft above ground.
8" D.Fir bears S.22°E., 22.1 ft well healed scar & BLM tag.
8" D.Fir bears N.37°30'W., 33.2 ft. well healed scar and BLM tag.
46" D.Fir bears N.4°W., 63.2 ft Old axe work and illegible old rusted tag No record fd for this BT
Corner lies on steep east slope approx 900 ft W of Hubbard CR