

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 21 & 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

**ON THE COOS COUNTY LINE - SEE COOS COUNTY SURVEYORS OFFICE FOR POSSIBLE ADDITIONAL RENEWAL REPORTS**

GLO survey by John W. Meldrum, Deputy Surveyor, under contract No. 662, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4759)

-----

Set hemlock post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd: ¼ S on W face, from which  
 A hemlock, 13" dia., bears N.72°E., 34 lks., mkd: ¼ S BT.  
 A maple, 10" dia., bears N.21°W., 29 lks., mkd: ¼ S BT.

BLM Dependent resurvey by Wayne Rogers, Cadastral Surveyor, under Group #350, surveyed June/July 1973 - (DCSO records Vol. 39 Page(s) 15960)

-----  
The ¼ sec. cor. of secs. 21 & 22, determined at rec bearing & distance from the remains of the original BTs:

A hemlock stump, 16" dia., bears N.72°E., 34 lks., no marks visible.

A maple, 16" dia., bears N.21°W., 29 lks., with scribe mark B visible on opened blaze.

and bearing trees of which I have no record

A hemlock, 10" dia., bears N.64°E., 42 lks., with scribe marks ¼ S22 BT visible on open blaze.

A cedar, 12" dia., bears S.45°W., 33 lks., with scribe marks ¼ S21 BT visible on open blaze.

At the corner point

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd.

T26S R9W  
 ¼  
 S 21|S 22  
 1973

Tony Hostetter - For: WEYCO - Jan. 2013 - C.S. File 65/78-4

-----

Found - 1973 BLM brass cap  
 Cedar BT is down with a 60" Fir stump on top of it.  
 Other BTs gone. From which:

- New BTs-
- 10" fir, scribed "S22 ¼ BT", WEYCO tag, bears; N.69°41'E., 8.9 ft to spike in root collar.
  - 10" fir, scribed "S.22 ¼ BT", WEYCO tag, bears; S.32°36'E., 12.9 ft to spike in root collar.
  - 16" hemlock, scribed "S22 ¼ BT", WEYCO tag, bears; S.15°E., 3.2 ft to spike in root collar.
  - 16" fir, scribed "S21 ¼ BT", weyco tag, bears; S.16°42'E., 36.9 ft to spike in root collar.