

PRIMARY CORNER DESCRIPTION Cor. Secs. 2, 3, 10, & 11

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by John W. Meldrum, Deputy Surveyor, under contract No. 662, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4752)

-----

Set chinkapin post 3 ft. long, 3" sq., 24" in the ground for cor. of secs. 2, 3, 10, & 11, mkd: T26S, S2 on NE, R9W, S11 on SE, S10 on SW S3 on NW faces, with 5 notches on S & 2 notches on E edges, from which:

- A hemlock 10" dia. bears N.58°E. 10 lks mkd: T26S R9W S2BT
- A fir, 12" dia. bears S.60°E. 47 lks. mkd: T26S R9W S11 BT
- A fir, 7" dia. bears S.38°W., 12 lks. mkd: T26S R9W S10 BT
- A hemlock, 12" dia., bears N.84°W., 38 lks., mkd: T26S R9W S3 BT.

Robert C. Adamek, Weyerhaeuser Co. Dellwood Engineering Office Williams River No. 2 survey - March 27, 1975 - M55-60 & C.S. File 58/42

-----

Found - 1" IP set by Weyerhaeuser Co. engineers. Orig. BTs for pipe were destroyed by road construction. Corner was re-re-referenced as follows:

- 8" Hemlock bears N.37°W., 6.1 ft.
- 24" Madrone bears N.76°E., 5.5 ft.
- 18" D.Fir stump bears S.13°E., 25.0 ft.
- 8" D.Fir bears S.60°W., 23.4 ft.

Douglas Co. Surveyors Office - Randall Smith - Stephen Flause - July 30, 1992 - C.S. File 64/31-2

-----

Found - A 1" O.D. Iron pipe protruding 7" above ground. (Set by Weyerhaeuser Co.) 1975

- 8" now 12" dia. 3 ft. high Hemlock stump; with a fully healed single blaze, bears N.46°W., 6.1 ft. (Rec. N.37°W., 6.1 ft.) 1975
- 24" now 18" dia., 3 ft. high Madrone stump with a previously opened rotted blaze, bears N.66°E., 5.5 ft. (Rec. N.76°E., 5.5 ft.) 1975
- 18" now 18" dia. 2 ft. high D.Fir stump, rotted shows old axe marks & "W" nail laying along stump bears S.13°E., 26.1 ft. (Rec. S.13°E., 25.0 ft.) SW BT from 1975 is gone.

New BT - 18" dia. 2 ft. high D.Fir stump with boat spike set through BT tag near center of stump, BS bears S.50°E., 26.7 ft.

Corner is approx. 40 ft. North of a gravel road and 10 ft. East of a cat road in a clear cut.