

PRIMARY CORNER DESCRIPTION South 1/4 Cor. Sec. 34 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>GLO Survey by Samuel C. Flint, Deputy Surveyor, under Contract No. 473, dated June 5, 1883 - (DCSO Records Vol. 23 Page(s) 9829 &amp; Vol. 24 Page(s) 10244)</p> <p>-----</p> <p>Set post 44x4" firmly in the ground for stan. ¼ sec. cor. mkd S C on N and S faces, from which</p> <p>    A fir, 18" dia., bears S.40°E., 21 lks., mkd: S C ¼ S BT.</p> <p>    A fir, 16" dia., bears N.2°W., 27 lks., mkd: S C ¼ S BT.</p>
<p>GLO resurvey by Lincoln E. Wilkes, US Cadastral Engineer, Otto L. Draper &amp; Norman D. Price, US Transitmen, under Special Instr. dated Dec. 21, 1920 - (DCSO records Vol. 24 Page(s) 10266-7)</p> <p>-----</p> <p>The old established for standard ¼ cor. of Sec. 34 bears S.19¾°W., 63 lks. (and East 7.01 chs.)</p> <p>I destroy all evidence of this cor.</p> <p>Set an iron post, 3 ft. long, 1" dia., 28" in the ground, for standard ¼ sec. cor., with brass cap marked</p> <p style="text-align: center;">SC ¼ S 34 ----- 1927</p> <p>from which</p> <p>    A fir, 14" dia., bears N.75°E., 21 lks., mkd: ¼ S34 SC BT.</p> <p>    A fir, 30" dia., bears N.55°W., 57 lks., mkd: ¼ S34 SC BT.</p> <p>(1/4 Cor. Sec. 3 bears West 1.61 chs.)</p>
<p>BLM Mineral Survey 1008 A&amp;B by Richard C. Skinner, Mineral Surveyor, survey under order dated June 30, 1992, Survey of Mineral Claims of: Anna Lu Rannells, Surveyed July/Aug. 1992 - (DCSO records Vol. 50 Page(s) 18932)</p> <p>-----</p> <p>The standard ¼ sec. cor, of sec. 34 only, T27S R1E WM monumented with a 1" dia., iron post, 10" above the ground, firmly set, with a 2½" dia. GLO brass cap properly marked, from which the original BTs are at record measurements and in good condition.</p>