

TOWNSHIP 27 RANGE 01 POINT IDENTIFIER # 140400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 18 & 19

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Homer D. Angell, Deputy Surveyor, under contract #747, dated May 5, 1902 - (DCSO records Vol. 11 Page(s) 4849)

Set a basalt stone 15x12x7", 10" in the ground for ¼ sec. cor. mkd. ¼ on n face, from which
A fir, 40" dia., bears N.30°E., 48 lks., mkd: ¼ S18 BT.
A hemlock, 30" dia., bears S.39°E., 50 lks., mkd: ¼ S19 BT

Douglas Co. Surveyors Office - John Powell - Frank Jones & W. Penley - Dec. 1969 - C.S. File 54/94

Reported as not found.
This cor. falls in old clear cut unit heavy brush cor. not found.

BLM dependent resurvey by Jasper M. Sams & Donovan C. Harris, Cadastral Surveyors, under Group No. 747, surveyed June/Aug. 1971 - (DCSO records Vol. 35 Page(s) 14577)

Point for the ¼ sec. cor. of secs. 18 & 19, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28 long, 2½" dia., 21" in the ground, and in mound of stone, 2½ ft. base, to top with brass cap marked:
T27S R1W
¼ S 18
 S 19
1971

from which
A fir, 5" dia., bears S.62°E., 20 lks., mkd: X BT.
No other suitable trees available within limits.

Ronald A. Quimby, LS 1654 & Romanso E. Ware, LS 1005 - For: USFS - March 1980 - M 82-70

Found - 60" D.Fir snag bears N.30°E., 31.7 ft., opened and found visible scribes "4".
40" Hemlock snag bears S.39°E., 33.0 ft. with good face but rotted out.
Found stone but unable to identify marks.
Set - 2½" Iron pipe with brass cap in a mound of stone.
BTs - 6" D.Fir bears N.74°W., 6.9 ft., scribed "¼ S18 BT"
12" D.Fir bears S.70°E., 12.1 ft. scribed "¼ S19 BT"
9" D.Fir bears N.20°E., 4.8 ft. scribed "¼ S18 BT"
Set fiberglass post with sign. Brass washers in BT faces RLS #1654.

continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 18 & 19

Alias	Description
Alias	Description
Alias	Description
Alias	Description

BLM Dependent resurvey by Wayne Rogers, Cadastral Surveyor, under Group #747, surveyed June 1980 - (DCSO records Vol. 42 Page(s) 16468-9)

The ¼ sec. cor. of secs. 18 & 19, perpetuated & recorded by Quimby in 1980, monumented with an iron post, 2½" dia., firmly set, projecting 6" above ground, with brass cap mkd.

T 27 S

¼ S 18
S 19

R 1 W

1980 RLS 1654

from which the remains of the original bearing trees

A fir snag, 45" dia., bears N.30°E., 48 lks., with scribe marks ¼ visible on opened double blaze.

A fir snag, 42" dia. bears S.39°E. 50 lks with fragmentary scribe marks visible on decayed blaze. (Rec. hemlock) and bearing trees mkd. by Quimby

A fir, 9" dia., bears N.19½°E., 7½ lks., with scribe marks ¼ S18 BT visible on open double blaze.

A fir, 11" dia., bears S.73¼°E., 18½ lks., with scribe marks ¼ S19 BT visible on open double blaze.

A fir, 8" dia., bears N.75½°W., 10½ lks., with scribe marks ¼ S18 BT visible on open blaze.

From this point, the ¼ sec. cor. of secs. 18 & 19, erroneously positioned by Sams and Harris, in 1971, bears N.87°49'W., 1.72 chs., monumented with an iron post, 2½" dia., firmly set, projecting 6" above ground, with brass cap mkd. and witnessed as described in the official record. I remove the iron post and destroy the marks on the BT.