

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 32

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>GLO resurvey by Homer D. Angell, Deputy Surveyor, under contract #747, dated May 5, 1902 - (DCSO records Vol. 11 Page(s) 4843)</p> <p>-----</p> <p>Set a basalt stone 12x12x8", 8" in the ground for ¼ sec. cor. mkd. ¼ on N face, from which</p> <p> A fir, 14" dia., bears NE., 37 lks., mkd: ¼ S29 BT.</p> <p> A fir, 14" dia., bears S.2°E., 30 lks., mkd: ¼ S32 BT.</p>
<p>Douglas Co. Surveyors Office - John Powell - Frank Jones & W. Penley - Nov. 1969 - C.S. File 54/94</p> <p>-----</p> <p>Reported as not found.</p> <p>This corner probably fell in logging rd. Fd. old squared post above rd. approx. 70.0 ft. abut no trace of any BTs.</p>
<p>Douglas Co. Surveyors Office - Gary L. Langlitz - Clell E. Goodwin, A V Cangie, M Lenora Ladig - 6/5/1975 - C.S. 57/30-5</p> <p>-----</p> <p>Found - Stone approx 8"x9"x12" approx. 4" in the ground & loose, with a faint "¼" marked on the apparent north face.</p> <p> We find no evidence of any corner accessories. The area adjacent to this corner has been logged & burned. We do not monument the corner at this time.</p>
<p>Ronald A. Quimby, LS 1654 & Romanso E. Ware, LS 1005 - For: USFS - March 1980 - M79-32</p> <p>-----</p> <p>Found - Rock out of place with "¼", unable to determine original location of corner stone.</p> <p>Set - 2½" iron pipe with brass cap at proportionate location.</p> <p>BTs - 6" Pine bears S.11°W., 19.6 ft. scribed "¼ S32 BT"</p> <p> 8" Hemlock bears N.4°E., 24.3 ft. scribed "¼ S29 BT"</p> <p>BTs have brass washers RLS# 1654 in BTs face.</p>
<p> </p>