

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 21 & 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO resurvey by Homer D. Angell, Deputy Surveyor, under contract #747, dated May 5, 1902 - (DCSO recs Vol 11 Pg 4825)

Set a basalt stone 20x10x8", 15" in the ground for ¼ sec. cor. mkd. ¼ on W face, from which
 A fir, 24" dia., bears S.72°E., 19 lks., mkd: ¼ S22 BT.
 A hemlock, 30" dia., bears N.50°W., 17 lks., mkd: ¼ S21 BT

Douglas Co. Surveyors Office - John Powell - Frank Jones & W. Penley - Nov. 1969 - C.S. File 54/94

Reported as not found.
This cor. probably destroyed by Little River Rd. conts.
Area below rd. badly burnt also some logging.

Jim S. Peterson - For: U.S.F.S. - November 1978 - M 70-41

Found no trace of original corner or BTs.
Set - 3" Brass tablet in rock outcropping.
BTs- 16" Fir, N.74¾°E., 65.2 ft. scribed "¼ S22 BT".
 12" Hemlock, N.54½°W., 6.1 ft. scribed "¼ S21 BT"

Les Fanning - July 7, 2008 - C.S. 65/64-23

Found - A 3" dia. brass tablet set in rock outcropping
 stamped: T27S R1W
 ¼
 S21 S22
 1978 PLS 1084
 from which bearing trees by Peterson in 1978:
 A 25" D. Fir bears N.74¾°E., 65.2 ft. with healed double blaze. (Rec. N.74¾°E., 65.2 ft.)
 A 22" uprooted Hemlock blown down to the SE over the rock outcropping creating huge root wad with boulders and soil hanging over corner monument, which is still accessible. (Rec. N.54½°W., 6.1 ft.)
New BT - A 17" Hemlock bears S.57°W., 20.8 feet, scribed "¼ S21 BT" on double face.
All new bearing trees have double blazed faces with a brass washer stamped "PLS 1941" nailed into the lower blaze. Bearings are taken to the center of the tree at the root crown and distances are measured to an aluminum nail in the root crown at the side and center of the tree.
All bearing trees have a 6" red band painted around the tree and the blazed face painted red and Bearing Tree and USFS Land Survey Monument sign nailed to the tree.

cont.

