

PRIMARY CORNER DESCRIPTION Sec. Cor. for 24 & 25 only, T27-3

Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by S.C. Flint, Contract #454, dated June 19, 1882 - (DCSO records Vol. 12 Page(s) 4860-61) and (Dup. Pg. #4983)

-----  
 Set Cedar post 4 ft. long, 4" sq., for cor. to secs. 24, 25, 19 and 30 firmly in the ground with 4 notches on the North and 2 on South edges mkd. T27S R2W S19 on NE.; R3W S24 on NW.; S25 on SW.; and R2W S30 on SE. faces, from which  
 A Fir 28" dia., bears N.15°E., 23 lks. dist. mkd. T27S R2W S19 BT.  
 A Laurel 10" dia., bears N.70°W., 34 lks. dist. mkd. T27S R3W S24 BT.  
 A Fir 20" dia., bears S.78°W., 35 lks. dist. mkd. T27S R3W S25 BT.  
 A Fir 28" dia., bears S.65°E., 44 lks. dist. mkd. T27S R2W S30 BT.

GLO Resurvey by Morris Wygant, Compassman for Zachariah Derrick, U.S. Deputy Surveyor, Under Contract #779, dated Feb. 7, 1908 - (DCSO records Vol. 12 Page(s) 4911)

-----  
 Intersect the cor. of secs.19, 24, 25 and 30 which is a post firmly set; A Fir 24" dia., mkd. T27S R3W S25 BT alone remains of bearing trees. A heavy forest fire of 1911 having destroyed the timber. I now change this cor. to refer to secs. 24 and 25 T27S R3W only.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew April 22, 1969 - C.S. File 54/40-164

-----  
 Found - Orig. 20" now 30" Fir S.78°W., 28.1 ft., now badly decayed remains of stump bark scribe R3W S25 R1.  
 Orig. 28" now 48" Fir S.65°E., 29.0 ft. alive, axe mark on bark. No scribe or scar.  
 No trace of other O.B.T.s at corner point.

Set 1" I.P. Brass cap at cor. mkd: County Surveyors Office  
 T 27 S  
 R3W  $\frac{S\ 24}{S\ 25}$  | R2W  
 1969

New BTs- 6" Hemlock N.83°E., 33.7 ft. mkd. T27S R2W S19 CSBT  
 18" D.Fir S.10°W., 2.0 ft. mkd. T27S R3W S25 CS BT.  
 8" Cedar N.71°W., 51.5 ft. mkd. T27S R3W S24 CS BT.  
 Cor. lies on very steep N. slope of spur & 217.8 ft. North of closing cor. of secs. 19 and 30, T27S R2W.

Fd. OK, August 1985 by R. Geisler - M 90-71

continued next page

PRIMARY CORNER DESCRIPTION Sec. Cor. for 24 & 25 only, T27-3

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM dependent resurvey by A. Bert Skeesick & Timothy J Moore, Cadastral Surveyors & Robert H Browning, Survey Technician, under Group No. 1968, surveyed Aug. 2003/July 2004 - (DCSO records Vol. 56 Page(s) 22036-7)

-----  
The cor. of secs. 24 & 25 only, remonumented by the Douglas County Surveyors Office in 1969, monumented with an iron post, 1½" dia., firmly set, projecting 10 ins. above ground, with brass cap (properly) mkd.

from which the remaining original bearing tree

A fir, 51" dia., bears S.65°E., 29.0 ft., no marks visible.

and bearing trees mkd. by the Douglas County Surveyors Office  
A hemlock, 10" dia., bears N.82°E., 33.4 ft., with a healed blaze.

A fir, 23" dia., bears S.8°W., 2.0 ft., with a healed blaze.

A cedar, 15" dia., bears N.71°W., 51.1 ft., with a healed blaze.

and a new bearing tree

A hemlock, 8" dia., bears N.24¼°W., 31.8 ft., mkd. T27S R3W S24 BT.

Ronald L. Rice, Ward NW - For: Seneca Jones Co. - April 2011  
- M162-30

-----  
Found - 1969 Douglas County brass cap with the following accessories:

51" D.Fir bears S.65°E., 29.0' - no marks visible

25" D.Fir bears S.8°W., 2.0' - healed face

15" W.Red Cedar bears N.71°W 51.1' - healed face

11" Hemlock bears N.82°E., 33.4' - healed face

9" Hemlock bears N.24¼°W., 31.8' - scribing visible