

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 30

| Alias | Description |
|-------|-------------|
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |

GLO resurvey by Morris Wygant, Compass man for Zachariah M. Derrick U.S. Dep. Surveyor, under contract #779, dated Feb. 7, 1908 - (DCSO records Vol. 12 Page(s) 4953)

N.0°04'W., bet. Secs. 29 & 30 at 40.00 chs.
Set a cedar post, 3 ft. long, 4" sq., 24" in the ground, for 1/4 sec. cor., marked 1/4 S30 on W & 29 on E face; from which
 A hemlock, 18" dia., bears N.33°E., 23 lks., mkd: 1/4 S29 BT
 A hemlock, 24" dia. bears N.9°50'W., 12 lks. mkd: 1/4 S30 BT
42.50 chs.
Derricks 1/4 sec. cor. which I now destroy, bears W 300 lks.
Note - We have no record of Derrick setting this corner.
 JC DCSO 9/2008

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - J. Heritage - V. Perron - Oct./Nov. 1968 - C.S. File 54/40-101

Found - Orig. 24" now 26" hemlock, down, N.10°E., 7.9 ft., find scribe on chopped out blaze. This BT fd. by Forrest appraisal, 1952.
 Find hole N.33°E., 15.2 ft., possible BT downhill & burned, no scribing found.
Set - Brass cap at cor. mkd: COUNTY SURVEYORS T27S R2W (6' steel fence post alongside) OFFICE 1968 1/4 S30|S29
New BTs- 5" yew S.37°E., 7.2 ft. mkd: 1/4 S29 CS BT.
 5" yew N.47°W., 51.3 ft. mkd: 1/4 S30 CS BT (dying)
 7" W.Fir S.51°W., 38.8 ft. mkd: 1/4 S30 CS BT (20' high broken top)
This corner lies in large clear cut about 330 ft. S of creek, course NE, now NW as in field notes.

Ronald Geisler, Champion International Corp. - June/Aug. 1985 - M90-71

Found - A 1968 brass cap (DCSO) on an iron post, with following accessories;
BTs - Orig. hemlock down and badly decayed. Root hole bears N.10°E., 7.9 ft.
 8" Yew bears S.37°E., 7.2 ft Scribing visible (1968)
 7" Yew bears N.47°W. 51.3 ft Scribing visible (1968)
 12" Fir, bears S.51°W., 38.8 ft. Closed face. (1968)
New BT - 5" Fir, bears S.89°W., 15.0 ft. Scribed: 1/4 S30 BT

continued next page

TOWNSHIP 27 RANGE 02 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 30

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

BLM dependent resurvey by A. Bert Skeesick & Timothy J Moore, Cadastral Surveyors & Robert H Browning, Survey Technician, under Group No. 1968, surveyed Aug. 2003/July 2004 - (DCSO records Vol. 56 Page(s) 22003)

The ¼ sec. cor. of secs. 29 and 30, remonumented by the Douglas County Surveyors Office in 1968, and perpetuated by Geisler, in 1985, monumented with an iron post, 1¼" dia., firmly set, projecting 15" above ground, with brass cap (properly) mkd.

from which the remains of the original bearing trees

A roothole bears N.33°E., 15.2 ft., no trunk remains.

A roothole bears N.10°W., 7.9 ft., no trunk remains.

and bearing trees mkd. by the Douglas County Surveyors Office

A yew, 8" dia., bears S.39½°E., 7.2 ft., with scribe marks /4 S29 CS BT visible on a partially healed blaze.

A fir, 18" dia., bears S.50°W., 37.5 ft., with a partially healed blaze.

A yew, 8" dia., bears N.47¾°W., 50.4 ft., with scribe marks /W S30 CS BT visible on a partially healed blaze. and a bearing tree mkd. by Geisler

A fir, 11" dia., bears S.83¾°W., 14.9 ft., with a healed double blaze.

and a new bearing tree

A fir, 15" dia., bears N.47°E., 6.4 ft., mkd. ¼ S29 BT.