

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 8 & 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Charles Roberts, US Deputy Surveyor under contract #759 dated Oct. 26, 1904 - (DCSO records Vol. 12 Page(s) 4892 & 11762)

Set a basalt stone 12x8x7", 9" in the ground for ¼ sec. cor. mkd. ¼ on W face, from which
A fir, 18" dia., bears N.66°W., 35 lks., mkd: ¼ S8 BT.
A fir, 18" dia., bears S.22°E., 37 lks., mkd: ¼ S9 BT.
I destroy old ¼ sec. cor. & marks on BTs.

Douglas Co. Surveyors Office - James W. Byron, Deputy - M. Godfrey, S. Bilow - Sept. 16, 1957 - C.S. File 49/15 (Water right for W.L. Strain)

Found - Both orig. BTs.
18" now 26" stump open, scribed "¼S" S.22°E. 24.4 ft
18" now 28" R.Fir N.66°W., 23.1 ft. I open & fins scribing "8S"
Also find 12x8x7" basalt stone mkd. ¼ on W face.
BTs check bearing & distances to stone at corner.
Set brass cap at corner & alongside of corner stone, mkd cap:
COUNTY SURVEYORS OFFICE 1957 ¼S 8|9 T27S R2W
New BTs- Blaze & rescribe orig. NW BT N.63°W., 22.9 ft. ¼ S8 CS BT.
Blaze & scribe 8" R.Fir N.21°E., 14.3 ft. ¼ S9 CS BT
Note - At west edge 3 ft. log.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Frank Jones - V. Perron - Nov. 1968 - C.S. File 54/40-134

Found - 1957 CS brass cap & BT as follows:
Orig. 18" now 30" Fir, alive, good cond. N.63°W., 22.9 ft., reblaze healing.
NE ren. BT gone completely due to clearing & USFS housing.
No trees suitable to east of line.
New BT - 11" Cedar S.58°W., 43.8 ft. mkd: ¼ S8 CS BT.
This corner lies in N-S fence on west side of US Govt. Trailer Park.

Dependent resurvey by Peter A. Peterson & Daniel L. Berry, Cadastral Surveyors, under Group No. 757, surveyed Aug./Sept. 1971 - (DCSO Records Vol. 35 Page(s) 14592)

The sec. cor. of secs. 8 and 9, perpetuated by Tracy in 1957, monumented with an iron post, 1" dia., firmly set, protruding 6" above ground, with brass cap (properly) mkd
continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 8 & 9

Alias	Description
Alias	Description
Alias	Description
Alias	Description

from which the remaining original bearing tree
A fir, 30" dia., bears N.66°E., 35 lks., with healed blaze and a tree marked by Tracy, in 1957
A cedar, 13" dia., bears S.58°W., 67 lks., with healed BT.
No other suitable trees available within limits.
The corner point is located In N-S fence Line.

Douglas Co. Surveyors Office - Ed Monrean, deputy - Randy Smith & Stephen Flause - Feb. 14, 1984 - C.S. File 62/16-10

Found - 1" IP w/BC at fence corner. 1957
Note - Did NOT locate original basalt stone.
BTs - Orig. 18", now 30" dia. fir stump, 3½ ft. high w/partially healed blaze bears N.63°W., 22.9 ft. (agrees w/1968 Ren. - Orig. notes, and 1971 BLM notes call N.66°W., 24.4 ft. & 23.1 ft., respectively.)
Orig. SW BT NOT found.
8" fir (new BT scribed in 1957 Ren.) bearing N.21°E. NOT fd.
11" cedar, now 14" w/well healed dbl. blaze bears S.58°W., 43.8 ft.
New BTs- 12" hemlock, dbl. blazed & scribed "¼ S8 CS BT" bears N.52°W., 49.6 ft.
Note - As there are no suitable trees in the area to the East, we reference the following:
The most Westerly SW corner of a concrete foundation (house) w/stone veneer, bears N.32½°E., 33.7 ft.
3¼" O.D. I.P. for a basketball hoop pole bears S.78°E., 56.4 ft. This pipe is located near the westerly edge & approx. at midpoint of a 20'x30' concrete slab.
Note - Monument is along the westerly edge of a government housing area w/fences running generally N, S, W, & Easterly. See sketch in file.

Fd. DCSO BC & accessories per record, M Heimburger, M157-50
Lat: 43°14'08.3583"N Long: 122°57'06.1736"W