

PRIMARY CORNER DESCRIPTION CC Secs. 4, 8, & 9

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Dependent resurvey by Peter A. Peterson & Daniel L. Berry, Cadastral Surveyors, under Group No. 757, surveyed Aug./Sept. 1971 - (DCSO Records Vol. 35 Page(s) 14592-3)

Point for closing cor. of secs. 8 & 9.
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

```

      S 4
     S 8 | S 9
    T27S | R2W
      C C
      1971
    
```

from which

A fir, 25" dia., bears S.27°E., 52 lks., mkd: T27S R2W S9 CC BT.

A maple, 12" dia., bears S.3°W., 80 lks., mkd: T27S R2W S8 CC BT.

From this point the orig. closing cor. of secs. 8 & 9, bears N.0°15'W., 0.02 chs., perpetuated & record by Tracy, in 1968, monumented with an iron post, 1" dia., firmly set, protruding 7" above ground, with brass cap (properly) marked from which the orig. BTs

A decayed alder stump, size indeterminate, bears S.60°E., 26 lks., no marks visible.

A maple, 17" dia., bears S.23°W., 70 lks., with scribe marks BT visible on opened blaze.

and trees mkd. by Tracy in 1968

A fir, 25" dia., bears S.61°E., 69 lks., with healed double blaze.

A yew, 12" dia., bears S.47°W., 76 lks., with scribe marks T27S R2W S8 CC BT visible on partially healed blaze.

From this same point, the cor. of secs. 4 & 5 only, bears S.89°29'W., 1.05 chs.

Ronald Geisler, LS 1988 - For: Champion International - Aug./Oct. 1984 - N90-60

Found - 1971 BLM brass cap/iron pipe.

Found a badly bent 1968 County brass cap which bears N.0°15'W., 1.4 ft.

Decaying maple stump bears S.03°W., 52.8 ft. Down maple nearby, shows visible scribing. (1971)

25" fir bears S.27°E., 34.8 ft. (Rec. 34.3 ft.) Closed face. (1971)

New BT - 6" cedar bears S.04°W., 96.4 ft. scribed T27S R2W S8 CC BT.