

PRIMARY CORNER DESCRIPTION Cor. Secs. 21, 22, 27 & 28

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO resurvey by Morris Wygant, Compass man for Zachariah M. Derrick U.S. Dep. Surveyor, under contract #779, dated Feb. 7, 1908 - (DCSO records Vol. 12 Page(s) 4940)

Set a cedar post, 3 ft. long, 4" sq., 24" in the ground for cor. to secs. 21, 22, 27, & 28, marked T27S S 22 on NE, R2W S 27 on SE, S 28 on SW, S 21 on NW faces, with 2 notches on S & 3 notches on E edges; from which

- A fir, 24" dia., bears N.68°40'E., 75 lks., mkd: T27S R2W S22 BT.
- A fir, 12" dia. bears S.68°E. 46 lks. mkd: T27S R2W S27 BT
- A fir, 10" dia. bears S.15°W. 40 lks. mkd: T27S R2W S28 BT
- A hemlock, 24" dia., bears N.31°30'W., 31 lks., mkd: T27S R2W S21 BT.

Derricks cor. for secs. 21, 22, 27 & 28 which I now destroy bears North 405 lks.

Note - We have no record of Derrick setting this corner.
JC DCSO 8/2008

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Oct. 1968 - C.S. File 54/40-95 (pg 2)

Reported as not found.
We find no Wygant BTs. We do find Obit Derrick BTs NW & SW.
We do find US Plywood tag calling for double proportion cor. also not fd. due to logging.

Dennis Gaylord, USFS & Deputy Co. Surveyor - Randal Lopez - Oct. 3, 1977 - C.S. File 59/40-28

Found - 24" stump (well rotted) bears N.68°40'E., 49.5 ft. Open & find scribing & reverse "22 BT"
All other BTs have been destroyed by logging activities.

Set - Using the only remaining BT stump for reference, I set a 2½" brass cap on a 1" galv. IP stamped:
COUNTY SURVEYORS OFFICE
T27S R2W S 21|S 22 1977
S 28|S 27

New BTs- 6" D.Fir bears S.26°30'W., 49.2 ft. scribed: "T27S R2W S28 CS BT" on a double blaze.
6" D.Fir bears N.83°W., 52.2 ft. scribed "T27S R2W S21 CS BT" on a double blaze.
9" D.Fir bears N.5°E., 19.1 ft. scribed "T27S R2W S22 CS BT" on a double blaze.
9" D.Fir bears S.48°E., 20.9 ft. scribed "T27S R2W CS BT" on a double blaze.

continued next page

TOWNSHIP 27 RANGE 02 POINT IDENTIFIER # 400300

PRIMARY CORNER DESCRIPTION Cor. Secs. 21, 22, 27 & 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Note - Corner lies in an old clearcut 200 ft. east of logging spur.

Note - Approx. 150 ft. north of this corner are two stumps with BLM BT signs & healed blazes. I opened both & found the scribing nearly all destroyed. These may be BTs from Derricks survey. Creek called for in GLO notes is 653 ft. north of corner as renewed. (Rec. 653.4 ft.)

BLM dependent resurvey by A. Bert Skeesick & Timothy J Moore, Cadastral Surveyors & Robert H Browning, Survey Technician, under Group No. 1968, surveyed Aug. 2003/July 2004 - (DCSO records Vol. 56 Page(s) 21988-9)

The cor. of secs. 21, 22, 27, and 28, perpetuated by the Douglas County Surveyors Office in 1977 from original evidence no longer in existence, monumented with an iron post, 1 1/4" dia., firmly set, projecting 3 ins. above ground, with brass cap (properly) mkd.

from which BTs mkd. by the Douglas County Surveyors Office

A fir, 22" dia., bears N.4 1/4°E., 18.7 ft., with a healed double blaze.

A fir, 21" dia., bears S.49°E., 21.1 ft., with a healed double blaze.

A fir, 15" dia., bears S.24 1/4°W., 49.1 ft., with a healed double blaze.

A fir, 16" dia., bears N.84 1/2°W., 52.0 ft., with a healed double blaze.