



PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 10

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Romanso E. Ware - For: US Forest Service -June 1978 - M70-24 & M70-27

-----  
Found - 10" W.Fir bears N.38°E., 42 ft. good scar (rec. Hemlock)  
20" Cedar bears N.78°W., 17.9 ft. "¼ S9 CS BT"  
8" Cedar snag bears N.40°W., 46.2 ft. "¼ S9 BT"  
Set - 2½" galv. IP w/3" brass cap mkd: T27S R2W ¼ S9 S10  
1978 RLS 1005 in rock mound.

-----  
BLM Dependent resurvey by James E. Jelley, Cadastral Surveyor under Group #351 surveyed April/May 1978 - (DCSO records Vol. 41 Page(s) 16175)

-----  
The ¼ sec. cor. of secs. 9 & 10, perpetuated & recorded by Tracy, in 1968, and further perpetuated by Ware, in 1978, monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, and in a mound of stone, 3 ft. base, to top, with aluminum cap (properly) mkd. from which the remains of the orig. BTs  
A W.Fir stump, 22" dia., bears S.73¾°W., 22 lks., no marks visible on decayed blaze.  
and the remains of BTs mkd by Corbin  
A root hole, bears S.54¼°E., 74 lks., with a down fir alongside, 20" dia., with scribe marks ¼ S10 BT visible on open blaze.  
A cedar snag, 10" dia., bears N.40°W., 70 lks., with scribe marks ¼ S9 BT visible on open blaze.  
and BTs mkd. by Tracy  
A fir, 12" dia., bears N.38°E., 63½ lks. with healed blaze  
A cedar, 18" dia. bears N.78°W., 27 lks. with healed blaze  
The corner monument established by Corbin, in 1957, was destroyed by subsequent logging.