

TOWNSHIP 27 RANGE 02 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>GL0 resurvey by Morris Wygant, Compass man for Zachariah M. Derrick U.S. Dep. Surveyor, under contract #779, dated Feb. 7, 1908 - (DCSO records Vol. 12 Page(s) 4938)</p> <p>-----</p> <p>S.0°01'E., on true line bet. secs. 14 & 15 45.00 chs. - Derricks ¼ sec. cor. which I now destroy, bears East, 25 lks. 50.35 chs. Set a Maple post, 3 ft. long, 3" sq., 24" in the ground, for ¼ sec. cor., marked ¼ S15 on W and 14 on E faces; from which A yew, 10" dia., bears N.20°E., 58 lks., mkd: ¼ S14 BT. A maple, 6" dia., bears S.39°W., 22 lks., mkd: ¼ S15 BT. Note - We have no record of Derrick setting this corner. JC DCSO 8/2008</p>
<p>Thomas E. Shrum, Jr. - For: US Plywood Corp. - Nov. 1962 - C.S. File 51/254-8</p> <p>-----</p> <p>Found - 10" yew N.20°E., 38.3 ft. Set - 2½" Alum. cap 7" Yew, N.48½°W., 40.7 ft. mkd: ¼ S15 BT. Orig. Maple is gone.</p>
<p>Douglas Co. Surveyors Office - Vernon "Ray" Tracy - J. Heritage - V. Perron - Oct./Nov. 1968 - C.S. File 54/40-110</p> <p>-----</p> <p>Found - U.S. Ply. Alum cap & BTs as recorded in 1962. Orig. 10" now 16" yew, dead N.20°E., 38.3 ft. scribe visible on open blaze. 7" Yew dead nearly tipped out N.48½°W., 40.7 ft. Set - 5/8" I.R. 5.0 ft. south & 5/8" IR 15.0 ft. S of corner. 6 ft. steel fence post alongside alum. cap. This corner lies in clear cut area. No trees or suitable stumps close for new BTs.</p>
<p>Romanso E. Ware, LS 1005 - For: US Forest Service - March/July 1978 - M70-27</p> <p>-----</p> <p>Found - 2½" alum cap on ¾" IR stamped USPC prop cor T27S R2W 1962 S15 S14 ¼ RE 4287 (cap reversed in field) 16" yewood (dead) N.20°E., 38.3 ft. (vis. scribe) 7" yewood (down) N.48½°W., 40.7 ft. (vis. scribe) 5/8" I.R. bears 5.0 ft. south. 5/8" I.R. bears 15.0 ft. south. Note - I rescribed 16" yewood, "¼ S14 BT" with washer stamped "RLS 1005"</p>