

TOWNSHIP 27 RANGE 02 POINT IDENTIFIER # 536100

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. for Sec. 2 only, T28-2

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch , U.S. Cadastral Engineer - under special Instructions, dated June 7, 1922 - (DCSO records Vol. 12 Page(s) 4965)

A point, 40.00 chs. West of the closing cor. of secs. 1 & 2; Set an iron post, 3 ft. long, 1" dia., 27" in the ground, for 1/4 sec. cor., of sec. 2 only with brass cap mkd.

1/4 S 2
1923

from which

A Fir 40" dia., bears S.41°E., 54 lks. dist. mkd. 1/4 S2 BT
A Yew 10" dia., bears S.16°W., 28 lks. dist. mkd. 1/4 S2 BT

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Oct. 1968 - C.S. File 54/40-94

Found - 1923 GLO brass cap, in place & properly marked.
40" now 46" Fir, dead, S.41°E., 35.6 ft., scribe visible "S2 BT"
10" now 13" Yew, alive, S.16°W., 18.5 ft., good condition, scribe visible.
New BT - 7" D.Fir S.26 1/2°E., 25.0 ft. mkd. 1/4 S2 CS BT.
Corner lies on S. slope about 310 ft. W. of angle point on So. line of sec. 35, T27-2.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew June 28, 1972 - C.S. File 54/40-199

Found all BTs as recorded. No trace of 1923 GLO brass cap due to cat fire trail. From bearing trees,
Set Brass cap at cor. mkd: County Surveyors Office

T27S
1/4 _____ R2W
S 2 T28S
1972

No new BTs marked.
This cor. lies 310 ft. W. of Angle point on N. side of cat fire trail and on S. side of clearcut unit.