

PRIMARY CORNER DESCRIPTION Stand. Cor. for 35 & 36 only (South)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by S.C. Flint, Contract #459, dated August 3, 1882
- (DCSO records Vol. 12 Page(s) 4867)

Set Fir post 4 ft. long, 4" sq., 24" in the ground for
standard corner for secs. 35 and 36, marked S C T27S R2W on
N.; S36 on E.; and S35 on W. faces, with one notch on E. and
5 notches on W. faces, from which
A Fir 14" dia., bears N.30°E., 23 lks. dist. mkd. T27S R2W
S36 BT.
A Fir 36" dia., bears N.62°W., 62 lks. dist. mkd. T27S R2W
S35 BT.
A Fir 10" dia., bears S.35°W., 45 lks. dist. mkd. T28S R2W
S2 BT.

Tied corner in GLO Resurvey by Morris Wygant, Compassman for
Zachariah Derrick, U.S. Deputy Surveyor, Under Contract #779,
dated Feb. 7, 1908 - (DCSO records Vol. 12 Page(s) 4903)

GLO survey by Fred Mensch, Deputy Surveyor, under Special
Instructions dated June 7, 1922 - (DCSO records Vol. 12
Page(s) 4963)

The standard cor. of secs. 35 and 36 which is a sound Fir
post, 4" sq., 12" above ground, properly marked. This is
evidently not the original corner established by Flint and
appears to have been set at the time of the Wygant resurvey
of this line, though not shown in the notes. From the corner
A Fir 40" dia., bears N.58°E., 55 lks. dist. Old bearing
tree, now dead. This tree appears to have been taken
in the Wygant resurvey and not recorded.
A Fir 10" dia., bears N.84°E., 62 lks. dist. mkd. T27S R2W
S36 S C BT. New BT.
A Fir 7" dia., bears N.1°W., 67 lks. dist. mkd. T27S R2W
S35 S C BT. New BT.
The original bearing trees are all destroyed by fire.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
Oct. 1968 - C.S. File 54/40-84

Found - Orig. BT, 40" Fir snag, 40 ft. high, N.58°E., 36.3
ft., scribe visible.
10" now 16" Fir, alive, N.84°E., 40.9 ft., shows
scar. Rescribe "T27S R2W S35 SC CS BT."
7" now 22" Fir, alive, N.1°W., 44.2 ft. scribe
visible on open blaze. Rescribe "T27S R2W S36 SC
CS BT."
Set Brass cap at cor. mkd:

(Cont. Next Page)

TOWNSHIP 27 RANGE 02 POINT IDENTIFIER # 600100

PRIMARY CORNER DESCRIPTION Stand. cor. Secs. 35 & 36 only (South)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

County Surveyors Office
T 27 S
S 35 | S 36 R2W
T 28 S
1968
Corner lies on East side of Red Butte Lookout Road.

Fd. OK, Aug. 2, 1976 by DCSO - C.S. File 59/18-11