

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. Sec. 13

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>Romanso E. Ware - For: US Forest Service - May 1977 - M65-20 ----- Set - 2½" IP with brass cap in rock mound. Cap stamped T27S R2W C ¼ S13 LS 1005 1977 10" Hemlock bears N.69°E., 35.2 ft. scribed "C¼ S13 BT" 24" Hemlock bears S.32°W., 28.7 ft. scribed "C¼ S13 BT"</p>
<p>Jim Landrum, USFS - Leonard Herzstein - May 17, 1982 - C.S. 62/15-11 ----- REFERENCED NOTES ONLY Found - 2½" IP with properly marked brass cap, firmly set, projecting 2" above 3 ft. dia. mound of stone, set by R. Ware LS #1005 in 1977. A steel fence post, firmly set with USFS signs #54-2 and #54-9 attached bears North 3.0 ft. 1977 1977 BT, a 12" Hemlock (½ dead) bears N.69°E., 35.2 ft. with scribe marks "C¼ S13 BT" and alum. washer stamped "LS 1005" visible on partly healed double blaze. A 25" Hemlock bears S.32°W., 28.7 ft. with scribe marks "C ¼ S13 BT" & alum washer stamped "LS 1005" visible on partly healed double blaze. Referenced - I reference corner position as described below & remove IP with brass cap & steel fence post. Set 60d nail in base of 68" D.Fir snag (on east side of tree) bears N.68¾°W., 32.9 ft. to center of nail head. Set 60d nail in top of 48" D.Fir stump (6" from NE edge) bears S.74½°E., 27.6 ft. to center of nail head. All available trees are scheduled to be cut. Corner lies in old dirt road which is now new road construction. I.P. with brass cap will be reset when timber harvesting and new construction has ended.</p>
<p>Maurice Farr, LS 1181, Leonard Herzstein, Randy Lopez USFS - Dec. 12, 1984 - C.S. File 62/15 ----- Corner was established by R. Ware LS 1005 in 1977. It was monumented with an iron pipe with brass cap. In 1982, the I.P./B.C. was referenced out and the monument removed by Jim Landrum, Deputy Co. Surveyor due to new road construction. I am unable to locate Ware's iron pipe removed in 1982. Found - A 12" hemlock (½ dead) bears N.73°E., (Rec. N.69°E.) 35.2 ft. with scribe marks "C¼ S13 BT" visible on partially healed double blaze. 1977 cont...</p>

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. Sec. 13

Alias	Description
Alias	Description
Alias	Description
Alias	Description

A 25" hemlock bears S.32°W., 28.7 ft. with scribe marks "C ¼ S13 BT" visible on partially healed double blaze. 1977
(Both BTs have a 1½" dia. alum, washer, stamped "LS 1005" nailed to lower blazes.)
A 60d nail in base of 68" D. fir snag (on east side of snag) bears N.68¾°W., 32.9 ft. to center of nail head. 1982
A 60d nail in top of 48" D. Fir stump (6" from NE edge) bears S.74½°E., 27.6 ft. to center of nail head. 1982
Set - At point of intersection of all record distances and of the bearings as noted, I dig a hole 34" deep in gravel road (USFS Road #2700-030) in bottom of hole, I place a 2½" dia. tin United States Tobacco Co. lid. I then set a 2¼" outside dia. I.P. 25" long with flared base in the hole with brass cap marked "T27S R2W C¼ S13 LS 1181 1984". Brass cap is now 9" below road surface in right wheel track with a 7"x10" alum. sign immediately on top of it.
New - I set a 4"x4" wood post, 6 ft. long, 2 ft. in the ground, as a guard post, bears S.89°E., 21.2 ft. with USFS signs #54-6 and #54-9 attached.
All available trees, as are existing BTs are scheduled to be cut (forty timber sale). Corner should be checked after timber is harvested for condition report. Corner is in USFS Rd. #2700-030, 2.9 miles from Little River Road. Tobacco Lid was placed at corner point as a memorial.