

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 23

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO Survey by Sam C. Flint, Under Contract #454, dated June 19, 1882 (DCSO Records Vol. 12 Page(s) 4998)  
-----  
Set laurel post, 3 ft. long, 3" sq., firmly in the ground for 1/4 sec. cor. mkd 1/4 S on E & W faces, from which  
    A fir, 18" dia., bears S.60°W., 59 lks., mkd: 1/4 S BT.  
    A fir, 16" dia., bears S.35°E., 37 lks., mkd: 1/4 S BT.

Douglas Co. Surveyors Office - Ben B. Irving, DSC - Wit: Milo Godfrey & Lester S. Kershner - May 14, 1947 - C.S. 38/187  
-----  
Rescribed old BTs, viz. Fir 35" dia., bears S.60°W., 38.9 ft. & a fir 30" dia., bears S.35°E., 24.4 ft. Set a 1" iron pipe with a brass cap stamped "County Surveyors Office 1/4 S 22 23"

Fd. 1984 by D. Bentz - M96-28A&B

BLM Dependent resurvey by Boyd W. Peterson & Mark D. Dixon, Cadastral Surveyors, under Group #1268, surveyed May/Sept. 1985 - (DCSO records Vol. 48 Page(s) 18220)  
-----  
The 1/4 sec. cor. of secs. 22 & 23, perpetuated & recorded by Irving, in 1947, monumented with an iron post, 1 1/4" dia., firmly set, projecting 2" above ground, with brass cap (properly) mkd.  
from which the remains of the original bearing trees  
    A sawed fir stump, 26" dia., bears S.69°E., 45 lks., with scribe marks 1/4 23 CS BT visible on bark blaze, facing SW. (Record S.35°E., 37 lks.) (Note: stump moved out of true position by road construction.)  
    A sawed fir stump, 42" dia., bears S.60°W., 59 lks., with scribe marks BT visible on bark blaze.  
and new bearing trees  
    A G.Fir, 12" dia., bears S.71 1/2° E., 21 lks., mkd. 1/4 S23 BT  
    A fir 8" dia., bears S.34 1/2°W., 45 lks. mkd. 1/4 S22 BT.

Fd. 11/1993 by D. Bentz - M118-16

Carl Sweeden - For: Jack Stubbs - Jan. 2017 - 2017-0007  
-----  
Condition report:  
Found - 2 1/2" DCSO BC flush w/ground.  
    14" fir BT stob, S.71 1/2°E., 14.25' (21 lks), tag, 6.5' tall  
    32" D.Fir BT stump, S.60°W., 59 lks, tag, rotting and bark gone.  
    15" D.Fir BT, S.34 1/2°W 45 lks, tag  
    18" D.Fir BT stump, S.69°E., 45 lks, no tag, bark gone