

PRIMARY CORNER DESCRIPTION W 1/16 Cor. Secs. 2 & 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Bureau of Land Management survey by Harold D. Corbin, Under Group #350 - Survey Aug/Nov. 1958 - (DCSO records, Volume 29 Page 12411-2)

Point for the W 1/16 sec. cor. of secs. 2 & 35
Set an iron post, 28" long, 2½" dia., 16" in the ground, to bedrock, and in a mound of stone, 2½ ft. base, to top, with brass cap marked:
W 1/16 $\frac{S\ 35}{S\ 2}$
1958

from which
A pine, 17" dia. bears N.20°E. 183 lks. mkd: W 1/16 S35 BT
A twin oak, 10" dia., bears S.31¾°E., 119 lks., mkd: W 1/16 S2 BT.
The corner falls on a spur, slopes S.; desc. 199 ft. over SW slope. Graveled & maintained access road, 30 lks., wide, bears NW & SE.

Bureau of Land Management Dependent Resurvey, Survey completed Aug. 4, 1981 by Wayne L. Rogers (DCSO records Vol. 45 Page(s) 17432)

The W 1/16 sec. cor. of secs. 2 and 35, monumented with an iron post, 2½" dia., firmly set, projecting 10" above ground, in a mound of stone, 2½ ft. base, to top, with brass cap (properly) mkd.
from which bearing trees mkd. by Corbin
A pine, 18" dia., bears N.27°E., 183 lks., with healed blaze. (Record, N.20°E.)
A twin oak, 14" dia., bears S.24°E., 119 lks., with healed blaze. (Record, S.31¾°E.)

Douglas Co. Surveyors Office - Stephen J. Flause - Kody Inda - March 2008 - C.S. File 67/25-54

Found - A 3¼" dia., BLM brass cap (properly) mkd on a 2½" outside dia., iron pipe is firmly set with top leaning approx. 1.2 ft. SW'ly from plumb. Top of monument is approx. 10" out of ground and stem protrudes from trail, monument probably disturbed by passing ATVs
Accessories measured from plumb position of mon.
A Pine, 18" dia., now 30" DBH P. Pine with fully healed double blaze bears N.20°E., 120.8 ft. (as per rec. 1958 - does not agree w/1981 bearing)
No evidence of SE Twin Oak, area was cleared for firewood.

continued next page

TOWNSHIP 27 RANGE 03 POINT IDENTIFIER # 520700

PRIMARY CORNER DESCRIPTION W 1/16 Cor. Secs. 2 & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New - Plumb position of BC is referenced out, monument removed & hole deepened. Monument is set at plumb position & is now firmly set protruding approx. 1" above ground.

An 8" DBH W.Oak double blazed & scribed "W 1/16 S2 CS BT" bears S.49°E., 52.3 ft.

A 15" DBH P.Pine double blazed & scribed "W 1/16 S2 CS BT" bears S.45°W., 47.6 ft.

A 20" DBH I.Cedar double blazed & scribed "W 1/16 S35 CS BT" bears N.75°W., 73.3 ft.

Note - Monument is on sparsely forested S-W slope approx. 300 ft. north from Thunder Mountain Rd. (BLM Rd. 342)

Compass decl. 16¼°E.