

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 11 & 14

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

GLO Survey by Sam C. Flint, Under Contract #454, dated June 19, 1882 (DCSO Records Vol. 12 Page(s) 5001)

Set chitten post, 3 ft. long, 3" sq., firmly in the ground for 1/4 sec. cor. mkd 1/4 S on N & S faces, from which

A cedar, 16" dia., bears S.25°W., 48 lks., mkd: 1/4 S BT.

A cedar, 18" dia., bears N.45°W., 14 lks., mkd: 1/4 S BT.

Douglas Co. Surveyors Office - Ben B. Irving, County Surveyor - Witnesses: H.C. Carey & R.C. Kerchner - April 4, 1945 - C.S. File 38/46

Orig. BTs in place, blazed & scribed old trees.
Drove 3/4"x5' 4' in ground.

FD. 2/1981, G. Grubb, M86-55

BLM dependent resurvey by Lance J. Bishop & Wayne L. Rogers, Cadastral Surveyors, under Group #1189, surveyed May/July 1984 - (DCSO records Vol. 47 Page(s) 17956)

The 1/4 sec. cor. of secs. 11 & 14, perpetuated & recorded by Irving, in 1945, monumented with an iron pipe, 1" dia., firmly set, projecting 8" above the ground.
from which the original bearing trees

A cedar, 41" dia. bears S.41 1/4°W., 48 lks. with fragmentary scribe marks visible on opened blaze. (Rec S.25°W.)

A cedar, 53" dia. bears N.61 1/4°W., 18 lks. with fragmentary scribe marks visible on opened blaze. (Rec N.45°W. 14 lks)

At the corner point
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd.

T27S R3W
1/4 S 11
 S 14
 1984

Deposit the iron pipe alongside the iron post.
Corner is located at intersection of fences, extending N, S, and E.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy-Stephen J. Flause - July 9, 1985 - C.S. File 62/28-13

Found - A BLM disk on a 2" dia. IP, protruding 7", above ground, mkd. "U.S. DEPT. OF THE INTERIOR T27S R3W 1/4 S11 S14 1984 BUR. OF LAND MANAGEMENT" (1984 BLM Unofficial Resurvey). With a 3/4" inside dia. IP along west edge of disk, protruding 9 ins, cont.

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 11 & 14

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

above ground per 1945 ren. and a 5/8" I.R. protruding 5" above ground, source unknown.

Orig BTs- 16" now a 40" diam. R.Cedar with a chopped into partially healed upper blaze, scribe visible "S", lower blaze is partially healed with scribing visible. Bears S.43°W., 31.7 ft. (Rec. S.25°W., 31.7 ft.)

18" now a 46" diam. R.Cedar with a chopped into upper blaze, no scribe visible, lower blaze is partially healed with scribing visible "CS BT" bears N.61°W., 10.9 ft. (Rec, N.45°W, 9.2 ft. is a face measurement).

New BTs- 9" B. Fir, double blazed and scribed "¼ S14 CS BT", bears S.77¾°E., 57.5 ft.

6" D.Fir, double blazed & scribed "¼ S11 CS BT", bears N.13°W., 41.1 ft.

Corner is approximately 500 ft. west of Old Cavitt Creek Rd.

Corner report 2/4/1986 CS 63/34-21
Fd. Ok 10/1997 - K. DeGroot, 1997-135 A&B
Fd. Ok 11/1998 - K. DeGroot, 1999-12
Fd. Ok by D. Edwards 6/2006 - M150-67

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2258, Surveyed April/June 2009 - (DCSO records Vol. 57 Page(s) 22671)

The ¼ sec. cor. of secs. 11 and 14, perpetuated by Smith, in 1985, monumented with an iron post, 2½" dia., firmly set, projecting 5" above ground, (alongside of which is an iron pipe, 1" dia., firmly set, projecting 8" above ground), with brass cap (properly) mkd. from which the original bearing trees

A cedar, 45" dia., bears S.41¾°W., 31.7 ft., with a healed blaze.

A cedar, 63" dia., bears N.61¼°W., 11.9 ft., with a healed blaze.

and the remains of bearing trees mkd. by Smith

A fir snag, 9" dia., bears S.78½°E., 57.8 ft., with a healed double blaze.

A fir, 14" dia., bears N.14¾°W., 41.0 ft., with a healed blaze.

Corner is located 1 ft. W. of a wood fence post at the intersection of barbed and woven wire fence lines extending N., S., and E.

2