

PRIMARY CORNER DESCRIPTION NE Cor. Matthews DLC #43

Alias	Description

<p>Original survey by Aaron Bowser, April 4, 1856, Approved 1858</p> <p>-----</p> <p>Set post, from which</p> <p>    A B.Oak 6" dia. bears S.35°W., 19 lks. dist.</p> <p>    A B.Oak 15" dia. bears N.20°W., 32 lks. dist.</p>
<p>Milo E. Godfrey, Deputy Co. Surveyor - Stoffel and Stone January 1964 - C.S. File 53/33-44</p> <p>-----</p> <p>Found - 19" B.Oak S.35°W., 12.5 ft., cut open and found           good reverse scribing "BT".</p> <p>          Stump hole of NW bearing tree.</p> <p>Set brass cap at cor. mkd: County Surveyors Office, 1964                                   T27S R4W NE. DLC 43</p> <p>New BTs - 13" D.Fir S.15°W., 57.8 ft. mkd. NE DLC 43 CS BT.           12" B.Oak N.67°W., 31.2 ft. mkd. NE DLC 43 CS BT.</p> <p>Corner lies 1.5 ft. North of an E. &amp; W. fence line.</p>
<p>Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 9/27/2000 - C.S. File 66/16-46</p> <p>-----</p> <p>Found - DCSO 1964 brass cap iron pipe protrudes 9" above           ground. 1.5 ft. North of a E-W fence.</p> <p>          6" now 19" dia., 12 ft. high B.Oak snag with a           previously opened rotted blaze, bears S.35°W.,           12.5 ft. (OBT)</p> <p>          12" now 19" dia., B.Oak with a fully healed double           blaze, bears N.67°W., 31.2 ft. (1964)</p> <p>          13" now down &amp; rotted, illegible scribing found,           D.Fir root hole bears S.15°W., 57.8 ft. (1964)</p> <p>New - 17" dia., B.Oak double blazed &amp; scribed "NE DLC 43           CS BT" bears South 10.0 ft.</p> <p>          13" dia., W.Oak single blazed &amp; scribed "NE DLC 43           CS BT" bears N.39°W., 44.6 ft.</p> <p>          6" dia., W.Oak double blazed &amp; scribed "X CS BT"           S.11°W., 25.2 ft.</p> <p>          Center of roundish pond along east side of Strader           Rd. bears S.56°W.)</p> <p>Note - Corner approx. 300 ft. west of topo map location.</p>