

TOWNSHIP 27 RANGE 04 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Cor Secs 27, 28, 33, & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Addison R. Flint, Contract #56 dated March, 1855 (DCSO Records, Volume 12 Page 5058)

Set post cor. to secs. 27, 28, 33 and 34, from which
A Cedar 15" dia. bears S.28°E., 16 lks. dist.
A Cedar 5" dia. bears N.84°E., 18 lks. dist.
A Maple 5 dia. bears S.79°W., 19 lks. dist.
A R.Fir 22" dia. bears N.35°W., 7 lks. dist.

James W. Byron, Deputy - Milo Godfrey; S.A. Bilow - December 1958 - C.S. File 49/130-10

Found - Orig. 5" now 24" Cedar N.84°E., 11.9 ft. I open and find good scribing "1L".
I also find badly rotted stump of orig. NW BT. No scribing found.
No other BTs found.

Set brass cap at cor. mkd: County Surveyors T27S R4W S28|S27
Office, 1959 S33|S34

New BTs- 12" Yewwood bears N.42°W., 18.3 ft. scribed S28
T27S R4W CS BT.
12" Cedar bears S.54°W., 8.5 ft. scribed S33 T27S
R4W CS BT.
15" Cedar bears S.12°E., 33.4 ft. scribed S34 T27S
R4W CS BT.
12" R.Fir bears S.88½°E., 69.2 ft. scribed S34 T27S
R4W CS BT. This BT across So. Deer Creek.
No trees near to Northeast.

Milo E. Godfrey, Deputy Co. Surveyor - Wm. Stoffel; Mike Stone - Oct/Nov. 1963 - C.S. File 53/33-28

Found - DCSO 1959 brass cap.
All three BTs mkd. in 1959 are still alive & in good condition:
12" yew N.42°W., 18.3 ft.
12" Cedar S.54°W., 8.5 ft.
15" Cedar S.12°E., 33.4 ft.
The 12" Fir S.88½°E., 69.2 ft. is uprooted & down.
New BT - 4" Yew N.11°E., 23.4 ft. mkd: S27 CS BT.
Corner is approx. 6 ft. North of E. & W. fence line.

Found OK by BLM Dependent Resurvey by James Jelley, April 1970 DCSO records, Volume 35 14460

Found OK by BLM Dependent Resurvey by Gordon Popken, Sept/Oct. 1974 (DCSO records, Volume 36 Page 14988)

cont.

