



TOWNSHIP 27 RANGE 04 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Byron's 5" Fir, now 12" with well healed double blaze, bears S.73°E., 52.5 ft. from Byron's cap. (BLM rec. 52.1 ft.) and N.85½°E., 49.3 ft. from the BLM monument.

Byron's 12" Fir now 16" with well healed double blaze and with the face oriented S.50°E. Found per BLM rec. from Byron's cap, N.46°W., 23.8 ft. Also bears N.26°W., 39.6 ft. from the BLM corner.

BLM's 9" Fir now 10" with well healed blaze, found per BLM record from BLM cor. S.20°E., 15.2 ft.

BLM's 8" Fir with well healed blaze bears N.70°W., 20.2 ft. from the BLM corner. (BLM rec.19.8')

Evidence of thorough search by BLM.

Byron incorrectly proportioned this corner in 1959 per survey M 14-42. BLM correctly proportioned this corner in 1975.

We cut off Byron's 1¼" I.P. and place a yellow plastic cap in-side pipe which is stamped "DOUG. CO. SURVEYOR" (sic)

---

Found OK, October 1994 by Dolan - M119-44.  
Found OK by N. Hibbs, Dec. 1999 - P. Plat 2000-0007 A & B

---

2