

TOWNSHIP 27 RANGE 04 POINT IDENTIFIER # 500400

PRIMARY CORNER DESCRIPTION Cor. Secs 14, 15, 22, & 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint, Contract #56 dated March, 1855 (DCSO Records, Volume 12 Page 5055)

Set post cor. to secs. 14, 15, 22 and 23, from which
A W.Oak 18" dia. bears S.81°W., 247 lks. dist.
A B.Oak 17" dia. bears S.3°E., 298 lks. dist.
A B.Oak 12" dia. bears N.88°E., 197 lks. dist.
A W.Oak 22" dia. bears N.26°W., 270 lks. dist.

James W. Byron, Deputy - Milo Godfrey; S.A. Bilow - April 1959 - C.S. File 49/146 and M 14-42

No original BTs found.
Set brass cap at cor. mkd: $\frac{S15|S14}{S22|S23}$ T27S R4W County Surveyors Office 1959
New BTs- 32" Cedar N.9°E., 76.5 ft. scribed S14 T27S R4W CSBT
34" B.Oak bears S.89°E., 135.4 ft. scribed S23 T27S R4W CS BT.
See Note in File - See Map M 14-42 also.

Vernon R. Tracy, Doug. Co. Surveyors Office - Jack Heritage; E. West - August 23, 1967 - C.S. File 53/33-52

Found - 1959 County Brass cap firmly set, mkd. T24S R7W.
We change Tsp and range to "T27S R4W."
All BTs alive & in good condition.
The NE BT will be removed, leaving:
39" B.Oak S.89°E., 135.4 ft., shows scribe on unhealed blaze.
New BT - 30" B.Oak N.7°W., 252.6 ft. mkd. T27S R4W S15 CSBT.
No other suitable trees within 400 ft. of corner.
This cor. lies on hillside sloping West, approx. 75 ft. E. of road.

Bureau of Land Management - Glenn Baughman under Contract #52500-CT5-1116. Survey Oct./Dec. 1975 (DCSO records, Volume 39 Pages 15794-95)

Point for the cor. of secs. 14, 15, 22 and 23, at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long 2½" dia. 23" in the ground, with brass cap mkd. $\frac{T 27 S R 4 W}{S 15 | S 14}$
 $\frac{S 22 | S 23}{1975}$ from which
A Cedar 7" dia. bears N.40°E., 59 lks. dist. mkd. T27S R4W S14 BT. continued next page

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

A Cedar 8" dia. bears S.40½°E., 23 lks. dist. mkd. T27S R4W S23 BT.
A Cedar 10" dia. bears S.1°W., 52 lks. dist. mkd. T27S R4W S22 BT.
A Cedar 6" dia. bears N.37°W., 133 lks. dist. mkd. T27S R4W S15 BT.
From this point, a local corner established by James Byron, Co. Surveyors Off. in 1959, bears N.2°38'W., 0.60 chs. dist. monumented with an I.P. with brass cap. From which bearing trees mkd. by Byron:
A Cedar, 38" dia. bears N.9°E., 116 lks. dist. with healed blaze.
A Cedar 45" dia. bears N.43°E., 80 lks with healed blaze.
An Oak 36" dia. bears S.89°E., 206 lks. dist. with healed blaze.

L.E. Monrean - Deputy Co. Surveyor - Janet Lundeen; Randall Smith - February 10, 1984 - C.S. File 62/16-13

Found - 2½" I.P. with brass cap, protruding 8" above ground.
1¼" I.P. with 2½" county Surveyors brass cap, protruding 17" above ground, by Byron in 1959.
Byron's Cap bears N.1½°W., 39.3 ft. from the BLM cap. (BLM rec. N.2°38'W., 39.6 ft.)
Byron's 32" Cedar, now 32" with partially healed double blaze, bears N.9°E., 76.0 ft. from Byron's cap (Rec. N.9°E., 76.5 ft.) and also bears N.5°E., 115.5 ft. from BLM cap.
Byron's 40" cedar, now 52" with well healed double blaze, found per Byron's rec. N.43°E., 52.7 ft. and bears N.24°E., 83.6 ft. from BLM cap.
Byron's 34" B.Oak, now 38" with well healed double blaze, bears S.89°E., 136.0 ft. from Byron's cap (Rec. S.89°E., 135.4 ft.) and bears N.74°E., 139.9 ft. from the BLM cap (Note: Byron's scribing is for wrong section.)
Tracy's 30" B.Oak, (now 31" with well healed double blaze on 4 trunk B.Oak) bears N.7°W., 254.7 ft. from Byron's cap. (Rec. 252.6 ft.) and bears N.7½°W., 294.0 ft. from the BLM cap.
BLM's 7" cedar (now 8" with well healed blaze on triple trunk) bears N.42½°E., 39.0 ft. (BLM rec. N.40°E., 38.9 ft.) from the BLM cap.
BLM's 8" cedar (now 12" with partially healed blaze) bears S.43¾°E., 15.7 ft. (BLM rec. S.40½°E., 15.2 ft.) from the BLM cap.
BLM's 10" cedar (now 14" with well healed blaze) found per BLM record, S.1°W., 34.3 ft. CONT.

