

PRIMARY CORNER DESCRIPTION West 1/4 Cor. for Sec. 25 only

Alias	Description

(Orig. ¼ cor. for Secs. 25 and 26 was set by Addison Flint, Contract #56 in 1855 - See DCSO records, Volume 12 Page 5050)

GLO resurvey and retracement by Elmer F. Strickler, Under Special Instructions dated Jan. 22, 1917 (DCSO records, Volume 12 Page 5084)

Set an Iron post, 3 ft. long, 1" dia. 26" in the ground, for ¼ cor. of sec. 25 only, with brass cap marked:
¼
|S25
1917 from which
A Fir 28" dia. bears N.83°45'E., 72 lks. mkd. ¼ S 25 BT.
A Fir 26" dia. bears S.17°15'E., 46 lks. mkd ¼ S 25 BT.
This corner is 660 ft. above the creek.

Milo E. Godfrey, Deputy Co. Surveyor, Wm. Stoffel & M.Stone October 1963 - C.S. File 53/33-16

Found - Iron pipe with brass cap, pulled out of ground by uprooted tree.
41" Fir (N.83¾°E) 47.5 ft., shows good scar - true bearing N.77°E.
Fir S.17¼°E., 30.4 ft., uprooted & dead. Old axe scar visible.
Reset Gov't brass cap in ground at true corner position.
New BT - 17" D.Fir S.7°E., 39.4 ft. mkd. "¼ S25 CS BT".

Fd. Ok Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 2/23/2000 - C.S. File 66/14-36

BLM Dependent resurvey by A Bert Skeesick, Cadastral Surveyor and Robert H. Browning, Survey Tech, under Group No. 2189 surveyed June/Sept 2008 - (DCSO records Vol. 57 Page 22499)

The ¼ sec. cor. of sec. 25 only, perpetuated by Godfrey, in 1963, monumented with an iron post, 1" dia., firmly set, projecting 3" above the ground, with brass cap (properly) mkd from which the remains of bearing trees mkd. by Strickler
A fir, 47" dia., bears N.77¾°E., 47.5 ft., with a healed blaze. (Record, N.83¾°E.)
A roothole bears S.17¼°E., 30.4 ft., alongside of which is a fir trunk, 38" dia., with no marks visible.
and a bearing tree mkd. by Godfrey
A fir, 30" dia., bears S.6¼°E., 38.6 ft., with a healed double blaze.