

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 19 only, T27-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Addison R. Flint, Contract #56 dated March, 1855 (DCSO Records, Volume 12 Page 4968)

-----

Set 1/4 sec. post, from which  
 A Laurel 8" dia. bears N.23°W., 30 lks. dist.  
 A Fir 22" dia. bears S.45°E., 5 lks. dist.

GLO resurvey, by Elmer F. Strickler, Contract #36 dated March 14, 1917, Special Instructions dated Jan. 22, 1917 (DCSO records, Volume 12 Page 5032)

-----

Apportioned Distance, Set an Iron post, 3 ft. long 1" dia. 26" in the ground, for qr. cor. of sec. 19 only, T27S R3W, with brass cap mkd.

1/4  
 |S19  
 1917

from which

A Fir 40" dia. bears N.13°E., 21 lks. dist. mkd. 1/4 S19 BT.  
 A Fir 50" dia. bears S.87°E., 52 lks. mkd. 1/4 S 19BT.  
 This cor. is 460 ft. below the sec. corner.

Doug. Co. Surveyors Office - Gary L. Langlitz; Stephen J. Flause - Sept. 19, 1977 - C.S. File 59/40-18

-----

Found - 1917 GLO brass cap on 1" I.P. 20" long, loosely set alongside the broken lower portion of the 1917 I.P. Cap properly marked.  
 40" D.Fir now 54" blow down, bears N.13°E., 13.9 ft. We open well healed blaze & find plain scribe marks.  
 The remains of a 50" D.Fir now 54" rotten snag 10 ft. tall, bears S.87°E., 34.3 ft. No markings found.

Set at the location of the found 1917 Iron post, we set a 1" x 30" I.P. 27" in the ground with brass cap attached marked:

Douglas County Surveyor	T 27 S
1977	S 19 R
	1/4 3
	W

and deposit remains of 1917 I.P. alongside.  
 New BTs - 18" D.Fir double trunked at the base bears N.69°W., 39.2 ft. scribed "W 1/4 S19 R3W CS BT" on a double blaze.

(Cont. Next Page)

TOWNSHIP 27 RANGE 04 POINT IDENTIFIER # 700339

PRIMARY CORNER DESCRIPTION ¼ Cor. for Sec. 19 only, T27-3

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

10" Hemlock bears N.53°E., 32.0 ft. scribed "1/4 S19 CS BT" on a double blaze.
Fd. Ok by K Hoffine 3/2007 - M152-54
Douglas Co. Surveyors Office - John Pike - Stephen J. Flause - 3/10/2008 - C.S. File 67/25-31 ----- Fd. 1977 DCSO brass cap 1 live BT & 2 stump.
BLM Dependent resurvey by A Bert Skeesick, Cadastral Surveyor and Robert H. Browning, Survey Tech, under Group No. 2189 surveyed June/Sept 2008 - (DCSO records Vol 57 Pgs 22489-90) ----- The ¼ sec. cor. of sec. 19 only, perpetuated by the Douglas County Surveyor's Office in 1977, monumented with an iron post, 1¼" dia., firmly set, projecting 2" above the ground, with brass cap (properly) mkd. from which the remains of bearing trees mkd. by Strickler A roothole bears N.13°E., 13.9 ft., alongside of which is a fir trunk, 36" dia., with a healed blaze. A fir snag, 57" dia., bears S.87°E., 34.3 ft., with a healed blaze. and the remains of BTs mkd by the Douglas Co Surveyors Office A hemlock, 18" dia., bears N.53°E., 32.3 ft., with a healed blaze. A sawed fir stump, 18" dia., bears N.68¼°E., 38.4 ft., with a healed blaze. and a new bearing tree A cedar, 20" dia. bears S.33¼°E., 28.1 ft. mkd. ¼ S19 BT