

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint, Contract #56 dated March, 1855
(DCSO Records, Volume 12 Page 4969)

Set ¼ sec. post, around which a mound was raised as per
instructions.

GLO resurvey of portion of E. Bdy. by Elmer F. Strickler,
under Special Instructions dated Jan. 22, 1917 and Contract
No. 36 dated March 14, 1917 (DCSO records, Volume 12 Pg. 5036)

At apportioned distance, Set a granite stone, 14x8x3 ins., 10"
in the ground, for the qr. section corner, marked ¼ on West
face, from which

A W.Oak 9" dia. bears N.19°E., 663 lks. dist. marked
¼ S 6 BT.

A B.Oak 16" dia. bears S.88°W., 672 lks. dist. marked
¼ S 1 BT.

Milo E. Godfrey, Deputy Co. Surveyor; Stoffel; Stone
January 8, 1964 - C.S. File 53/33-3

Found - 14" W.Oak tree, in clump, N.19°E., 437.6 ft., opened
and found good scribing "S".

Did not find rock at corner. No trace of SW BT.
Corner and position for SW tree is in cultivated field.
Set brass cap at cor. mkd: County Surveyors Office, 1964

T27S R4W ¼ S1|S6 R3W

Set steel fence post alongside of brass cap.

Rescribe 14" W.Oak N.19°E., 437.6 ft. "¼ S6 CS BT.

New BT - 22" D.Fir N.6°W., 553.3 ft. mkd: ¼ S1 CS BT. This
BT is alongside old road, Buckhorn Creek to
Fall Creek.

Douglas Co. Surveyors Office - Randall Smith; S.J. Flause
Sept. 12, 1988 - C.S. File 62/55-4

Found - 1964 DCSO brass cap on a 1¼" O.D. I.Pipe measuring
27" long, found laying loose on top of ground
near position of corner.

Metal flanges to brass cap/IP found 6" below ground
Broken off metal post found along north edge of
flanges. (Cont. Next Page)

TOWNSHIP 27 RANGE 04 POINT IDENTIFIER # 700640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 1; & 6 of T 27-3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

9" now 17" dia. trunk of SE tree in a 45" dia. cluster of W.Oaks, SE trunk has a fully healed blaze and a partially healed previously opened lower blaze, no scribing visible, bears N.19°E 437.6 ft. (agrees w/record) Orig. BT.
22" now 29" dia. D.Fir with a fully healed single blaze bears N.6°W., 551.6 ft. (Rec. N.6°W., 553.3 ft. is to center of trunk (1963 BT)
Reset brass cap iron pipe at plumb position of found flanges. Set flush with ground. The marks "RESET 1988" are added to brass cap.
New Accessory: A White metal post and sign is set 1 ft. south of BC/IP.
Corner is in a field. No trees within a reasonable distance.

Douglas County Surveyor's Office, Randall Smith and Stephen Flause. March 31, 1993. C.S. File 64/41-16

Found - 2½" dia. brass cap on a 1¼" OD iron pipe, protruding 5" above ground. (BC/IP set flush with ground, cattle have stomped the ground around BC/IP to the point BC/IP now protrudes above ground.)
Both BTs found as recorded. BT's are to be removed, both BT's are dying.
New BTs - 9" DBH W.Oak (has apparent blaze; this is opened low to ground but no scribing is found) scribed ¼ S6 CS BT on a double blaze, bears N.34¼°E., 471.4 ft.
13" DBH W. Oak (the most northwesterly trunk of multi-trunk tree) scribed ¼ S6 CS BT on a double blaze bears, S.71¼°E., 443.8 ft. (bearing and distance to base of scribed trunk).
9" DBH W. Oak scribed ¼ S6 CS BT on a double blaze bears, N.48¼°E., 399.3 ft dist.
23" DBH W. Oak scribed ¼ S1 CS BT on a double blaze bears, N.33½°W., 518.5 ft dist.

Found OK by K. DeGroot, Feb. 2003 - 2003-0018 A&B
Fd. Ok by K. DeGroot, 8/2005 - M146-27