

TOWNSHIP 27 RANGE 05 POINT IDENTIFIER # 039030

PRIMARY CORNER DESCRIPTION S.S.E. Cor. A Rose DLC #39

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Addison R. Flint, Contract #28 dated July, 1854  
-----  
Set Post, from which,  
    A W.Oak 6" dia. bears N.10°W., 42 lks.  
    A B.Oak 7" dia. bears N.41°E., 59 lks.

---

Doug. Co. Surveyors Off. John M. Powell; Frank Jones; J. Brady - March 1, 1966 - C.S. 53/38-29  
-----  
Found - Iron rod 175.0 ft. from DLC Corner, see Map file M 5 - 47. (I find this dist. to be 175.4 ft.)  
        Also PK Nail over DLC corner.  
Move West 0.4 ft. to correct distance of 175.0 ft. and  
Set - 3/4" Iron rod West 20.0 ft. from reference point.  
      22" W.Oak, N.8°W., 29.4 ft. scribed S.E. DLC #39  
      CS BT.  
      18" Cedar S.30°E., 55.5 ft. mkd. with P.K. Nail.  
Note - Move this corner point West 0.4 ft. because of solid iron rod & information of 3/4" I.P. at DLC corner being badly bent at the time PK Nail was set for corner.

---

Found OK by Bentz, Nov. 1996 - P.P. 1997-0009

---

Mark Heimburger - For: JC Reeves Corp. - 1/2017 - M173-2  
-----  
Found - Bent 3/4" iron bar 1.2' below AC surface.  
      5/8" iron rod bears S.89°40'24"W., 16.90' (S.90°W., 16.66')  
      22" W.oak (now 9' tall stump) bears N.8°W., 29.4' w/healed blaze.  
      18" cedar (now 24") bears S.30°E., 55.5'

---

1