

TOWNSHIP 27 RANGE 05 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Sec. Cor. 30, 31 (& 25, 36 T. 27-6)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Elder & Gile - 1853 - Contract #31

Set - Post for corner from which:
BTs - A W. Oak, 26" dia. bears S.29°W., 182 lks. dist.
A W. Oak, 16" dia. bears S.13½°E., 287 lks. dist.
A W. Oak, 22" dia. bears N.40½°E., 150 lks. dist.
A G. Oak, 9" dia. bears N.32½°W., 188 lks. dist.

Douglas Co. Surveyors Office - Arthur Boyer - Wit. Claude Crocker; J.H. Wolford; B.A. Lane; Ted Shellabarger
1934-37-38 - Volume 4 Pages 50-58

This corner was gone but was set by proportional distances between ¼ to 25 and 30 and the ¼ to 31 and 36.
Set - ¾ x 30 iron rod for corner.
BTs - White Oak, 24" dia. bears N.30°E., 34.0 ft.
Laurel, 4 dia. bears N.87°E., 158.5 ft.
Black Oak, 6" dia. bears S.2°E., 41.5 ft.
White Oak, 18" dia. bears N.1°W., 146.0 ft.

Douglas Co. Surveyors Office - James W. Byron, Deputy Milo Godfrey; S.A. Bilow - June 23, 1959 - C.S. 49/62-2

Found - ¾" Bolt at corner and 2 BTs set by Crocker:
6" B. Oak, now 10" S.2°E., 41.5 ft. showing good scar, did not open.
18" W. Oak, now 24" N.1°W., 146.0 ft. showing good scar, did not open.
Clump of laurels bears N.87°E., 158.5 ft., did not find one marked for BT.
New BTs - 9" W. Oak, N.84°E., 42.0 ft. blaze & scribe "T27S R5W S30 CS BT."
10" B. Oak S.41½°W., 95.4 ft. blaze & scribe "T27S R6W S36 CS BT".

Donald Garrett - July 1971 - M 42 - 50

Bolt missing - Set 5/8" iron rod.

TOWNSHIP 27 RANGE 05 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Sec. Cor. 30 & 31 (& 25, 36 of T27-6)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Burton Holt - For: Mel Mendenhall - March 1981 - M 79 - 75

CORNER REPORT ONLY
Found - A 2" x 2" angle iron fence post 5 ft. tall set in
 concrete - 4 way fence junction. (no record)
 14" B. Oak bears S.43°W., 95.4 ft.
 12" W. Oak bears N.84°E., 42.0 ft.
The 5/8" iron rod set by Garrett is missing.
(This corner used as tie for M 79-75)

Found August 1990, M 112 - 12

Found OK by B. Shaner, Nov. 1997 - 1998-0022 A & B
Found OK by R. Quimby, Jan. 2001 - M136-57