

TOWNSHIP 27 RANGE 05 POINT IDENTIFIER # 100409

PRIMARY CORNER DESCRIPTION So. Meander Cor. W. bdy. Sec. 18

Alias 836090 Description MC  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Elder & Giles - Contract #31 - 1853  
-----

Intersect ~~right~~ left bank of Umpqua River, course E. and  
W. Set - Meander Post from which:  
    An Ash, 5" dia. bears N.12½°W., 14 lks. dist.  
    A Balm Gilead, 14" dia. bears S.82½°E., 138 lks. dist.

H.L. Eppstein; A. Boyer; N.E. Richardson - Sept. 27, 1936  
Vol. 4 Pg. 51  
-----

On Elks Island 3"x3" cedar post and 3/4" iron rod 24" long  
from which:  
    Ash, 6" dia. bark blaze bears S.38°E., 23.8 ft.  
    Ash, 6" dia. bark blazed bears S.87°W., 21.6 ft. marked  
    C.S.M.C. S.13-18 BT.

Searched for, not found, June 17, 1966 V.R.T.; C.S. 53/38-13  
Searched for, not found, 8/25/87, C.S. 62/45-14; L.E.M.

Douglas Co. Surveyors Office - Stephen J. Flause - Nov. 16,  
2011 - C.S. File 67/36-1  
-----

Reported as not found.

Found - A 3/4x24" iron rod showing evidence of having once  
    been driven into ground. This rod is now  
    severely bent and lying on its side  
    approximately 2" below surface.

No trees of right age in vicinity.

Position of fd. iron rod in relation to section  
    corner just to the south is checked using a  
    staff compass and an EDM. this measurement to  
    be approximately 6 ft. North and 7 ft. East of  
    the position of meander corner set in 1936.

A survey would be required to reestablish this  
    corner.

Note - Found I.R. is near NW tip of Elk Island in area  
    subject to much flooding and brush clearing in  
    the last 75 years.

Compass decl. 16½°E.