

TOWNSHIP 27 RANGE 06E POINT IDENTIFIER # 140200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 30 & 31

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO Survey by Samuel C. Flint, Under Contract #473, dated June 5, 1883 (DCSO Records Vol. 24 Page(s) 10170)

-----  
Set post 44x4" sqr. 12" in the ground for 1/4 sec. cor., marked 1/4 S on N face, from which  
A fir, 30" dia., bears N.10°W., 13 lks., mkd: 1/4 S BT.  
A fir, 12" dia., bears S.35°W., 20 lks., mkd: 1/4 S BT.

Douglas Co. Surveyors Office - Dennis Gaylord, USFS & DCSO Deputy - Sept. 7, 1977 & Aug. 9, 1979 - C.S. File 59/40-1

-----  
RECORDED AS NOT FOUND  
Sept. 7, 1977  
~~Found - Orig. 12" now 26" White Fir bears S.35°W., 13.2 ft.  
Has a healed blaze.  
Bearing tree to the NW is gone.  
Set - Referring to the only BT remaining, I SET a 2 1/2"  
Brass cap on a 1" iron pipe stamped  
County Surveyors Office  
T27S R6E  
1/4 S30  
1/4 S31  
New - A 27" D.Fir bears N.17°E., 18.4, scribed "1/4 S30 CS  
BT" a double blaze. Placed County BT signs both  
original and new BTs.  
Corner lies approx. 300 ft. North of Diamond Lake.~~

Aug. 9, 1979  
"I questioned the validity of the tree which I assumed to be the orig. BT when I renewed this corner on 9/7/77, so I opened the blaze with a chain saw & found that there was no scribing on the face, thus this tree is **not** an original BT. **I removed the brass capped monument and destroyed (obliterated) the scribing on the new Bearing Tree** I marked on 9/7/77. I then used a staff compass & steel chain & chained from the corner secs. 29, 30, 31, 32, 1/2 mile west & made an extensive search for original evidence, but found none." Dennis Gaylord (USFS, DCSO Deputy)