

TOWNSHIP 27 RANGE 06 POINT IDENTIFIER # 300700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4 & 5; 32 & 33, T.26-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Set post cor. to Sec. 4, 5, 32 & 33, from which
A Maple 18" dia. bears N.9°W., 70 lks.
A Maple 15" dia. bears N.32½°E., 73 lks.
A Maple 36" dia. bears S.63°W., 196 lks.
A Maple 22" dia. bears S.24¾°E., 662 lks.

H.L. Eppstein; Roscoe Conn; Kenneth Conn; - Nov. 1933
C.S. 18/39 - "Old" Ren. Cor. Vol. 1 Pg. 93

A stone is buried in ground for this corner, witness trees in Section 5, 32, 33 in place. Tree in Section 4 gone. No trees near.

James W. Byron, Deputy Co. Surveyor - Milo Godfrey
January, 1961 - C.S. File 49/79-19

Found - Orig. 18" now 50" Maple, N.9°W., 46.2 ft., center burned out, now shell only, no scribing fd. All other BTs gone. We find 2" x 8" x 18" stone 6" under surface & under N.-S fence. Stone set on end.
Set - Brass Cap at corner & alongside cor. stone mkd:
County Surveyor's S32 | S33 T26S
Office, 1961 S 5 | S 4 T27S R6W
New BTs - 36" Maple bears N.14¾°W., 51.6 ft. scribed S32 T26S R6W CS BT.
10" Myrtle bears N.51°W., 113.7 ft. scribed S32 T26S R6W CS BT.
No other trees near.

Found OK 12/83, G. Baughman, M 95 - 71
Found OK 2/90, M. Heimbürger, M 109 - 57 A&B

Douglas Co. Surveyors Office - Randall Smith; Stephen Flauser
February 21, 1990 - C.S. File 64/5-15

Found - A 3" x 8" x 24" stone set on end, top approx. 6" below ground. (Rec. 2"x8"x18" in 1961) Top 9" is broken off and fractured into 3 pieces. (Probably broken when field was plowed). No marks fd. on stone. Stone set in 1933.
A 2½" dia. DCSO brass cap on a 1¼" O.D. x 36" long split end IP is fd. laying on top of ground approx 4 ft south of fd. stone. Top of BC/IP shows evidence of being hit by a plow. cont

TOWNSHIP 27 RANGE 06 POINT IDENTIFIER # 300700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4 & 5; 32 & 33, T.26-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

(Brg. & Dist. taken from top of center of stone:
A bent metal fence post is fd along east edge of stone. Source unknown.
10" now 20" dia. Myrtle with healed scars, we open in three places, no blazes or scribing found, bears N.54¼°W., 113.7 ft. (Rec. N.51°W., 113.7) Possible NW BT from Byron, 1961.
No other orig. or Renewal BTs found.
Set - A 5/8"x 30" long iron rod is set 2½ ft. below ground at referenced position of fd. stone. Stone is reset on end on top of 5/8" I.R. at referenced out position. DCS0 BC/IP is reset 0.2 ft. west of stone, along west edge of stone. The marks "RESET 1990" are added to BC. Stone is set 4" below ground, DCS0 BC/IP protrudes 2" above ground.
New BTs- 12" Cottonwood double blazed & scribed "T27S R6W S4 CS BT" bears S.7½°E., 276.1 ft.
28" Myrtle double blazed & scribed "T27S R6W S5 CS BT" bears S.84½°W., 301.8 ft.
18" Cottonwood double blazed & scribed "T26S R6W S32 CS BT" bears N.20°W., 134.0 ft.

DCS0-GIS Corner visitation - 6/18/2004 - Typed: 1/26/2011 - C.S. File 67/33-1

Monument - BC/IP - 1.25"
Comment - (needs) rehab