

TOWNSHIP 27 RANGE 07 POINT IDENTIFIER # 043020

PRIMARY CORNER DESCRIPTION NW Ext. Cor. Arant DLC #43

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Survey by J.A. Burnett, under Contract dated June 8, 1857

Set a post, from which
A W.Oak 10" dia., bears S.63½°E., 66 lks. dist.

Ben B. Irving - Wit. N.E. Richardson; Alvin Anderson
November 19-21, 1929 - C.S. File 37/14

Location identified from O.B.T., a 24" W.Oak scribed C.43
27S 7W.
Set post scribed "N.W. Cl. 43 C.S.", from which
The Orig. BT bears S.63½°E., 66 lks. which I reblazed
and scribed N.W. Cl. 43 C.S. B.T.
A new BT, A W.Oak 16" dia., bears S.40°E., 76 lks.
scribed N.W. Cl. 43 C.S. B.T.

Doug. County Surveyors Office - James W. Byron, Deputy
Milo Godfrey; S.A. Bilow - May 1957 - C.S. File 49/111
and RM 1-24

Found - 3/4" Iron pipe at corner and stump of orig. SE
BT, no scribing found, stump partly rotted
checks bearing & distance.
BBI SE BT., now 24" W.Oak snag scribing fair
condition, checks distance to corner. Bearing
recorded S.40°E., I find bearing should be
S.35°E.
Blaze and Scribe:
6" W.Oak S.60°E., 75.6 ft. "N.W. Cl. 43 CS BT".

Referenced out for road work - DCSO - John Powell - May 30,
1973 - C.S. File 59/3

Doug. County Surveyors Office - Larry E. Monrean, Deputy
S. Flause - March 3, 1977 - C.S. File 59/31-5

Found - Orig. 10" W.Oak now a rotted stump, face split
away, no scribing found. Stump bears
S.63½°E., 43.6 ft.
A W.Oak 16" now down & rotted bears S.35°E., 50.2
A W.Oak 6" now 8" bears S.59°E., 75.6 ft. (Rec.
S.60°E) Tree has well healed blaze.
Set 5/8" x 30½" Iron rod at NW corner DLC #43. Rod set 7"
below surface of graveled road.
(A Narrative is filed in C.S. File)

TOWNSHIP 27 RANGE 07 POINT IDENTIFIER # 043020

PRIMARY CORNER DESCRIPTION NW Ext. Cor. Arant DLC #43

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Found OK, Nov. 1993 by D. Bentz - Partition Plat 1994-0008.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - 2/3/1999 - C.S. File 66/8-26

Found: 5/8" iron rod is found 7" below gravel road
surface. 1977
10" now 24" rotted oak stump, bears S63½°E, 43.6
ft. OBT
6" now 12" dia. 2 ft. high w. oak stump with a
fully healed blaze, bears S60°E, 75.6 ft. 1957
1" i.d. iron pipe found 7" below road surface (SW
COR DLC 44), bears S87 3/4°E, 68.4 ft. M48-75
NEW: 5/8" I.R. bears N75½°W, 51.5 ft.
5/8" I.R. bears S64½°E, 76.1 ft.
5/8" I.R. bears S71½°W, 52.7 ft.