



TOWNSHIP 27 RANGE 07 POINT IDENTIFIER # 100140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 31; Sec. 36 of T 27-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

12" now 12" dia. down and rotted D.Fir scribing visible "BT" large root hole agrees with rec. "S.67°E., 26.2') 1930 DCS0.

9" now 16" dia. Cedar, with a fully healed double blaze, bears N.66°E., 39.8' (agrees with rec.) 1958 DCS0

Set- DCS0 BC/IP returned to plumb position, protrudes 6" above ground.

Corner lies at the intersection of a N-S and east running fence lines.

Fd. Ok by Tony Hostetter - For: Seneca Jones Timber Co. - Aug. 2002 - M140-72