

TOWNSHIP 27 RANGE 07 POINT IDENTIFIER # 240100

PRIMARY CORNER DESCRIPTION South ¼ Cor. Sec. 32 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Under Contract #57 dated April 12, 1855 (DCSO records, Volume 12 Pg. 5225)

Set ¼ sec. post, from which
 A B.Oak 20" dia., bears N.80°E., 63 lks. dist.
 A Laurel 20" dia., bears S.60°E., 51 lks. dist.
(¼ post, set by Ford, bears North 456 lks. and East 307 lks.)

GL0 survey by Fred Mensch, Under Contract #109 dated 1924 (DCSO records, Volume 14 Page 5849-50)

Intersect the ¼ sec. cor. of sec. 32, located by measurement from the original bearing trees. Only the stump of the NE tree remains on which the marks are plain. Marks on the SE tree are rotted away, but signs of the old blazes are plain. At the exact cor. point, Set an Iron post, 3 ft. long 1" dia., 28" in the ground, with brass cap mkd: $\frac{1}{4} \frac{S32}{1924}$

from which (new bearing trees)
 A Fir 40" dia., bears N.40°E., 13 lks. dist. mkd. ¼ S32 BT.
 A Fir 8" dia., bears N.58°W., 67 lks. dist. mkd ¼ S32 BT.
Stump of orig. NE BT, an Oak, 24" dia., bears N.80°E., 63 lks. The orig. SE BT, a Laurel 28" dia., bears S.60°E., 51 lks. dist.
(The cor. established by Ford for ¼ sec. cor., restored as angle point, bears N.33°57'E., 5.50 chs.)

Doug. County Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam - Feb/March 1961 - C.S. File 49/79-39

Found - Brass cap at ¼ corner.
 NE BT now stump only.
 SE BT, center rotted.
 NW BT, stump, shows good scar.
New BTs - 8" R.Fir bears N.67°W., 45.7 ft. scribed ¼ S32 CSBT.
 9" R.Fir bears N.44°E., 24.5 ft. scribed ¼ S32 CSBT.

Fd ok by Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - 5/6/1998 - C.S. File 66/2-28

Fd. BC by N. Hibbs - 3/2019 - M175-31