

PRIMARY CORNER DESCRIPTION Angle Point No. 9

| Alias | Description |
|-------|-------------|
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |

GLO survey by Fred Mensch under Contract #109 dated 1924
(DCSO records Vol. 14 Pages 5858 & 5872)

NOTE -Angle Point No. 9 is mentioned on the above given pages but no description of the monument set or the BTs scribed are given any where in Mensch's survey notes (Vol. 14 Pages 5833 - 5881) nor in the BLM microfilm.

BLM dependent resurvey by Philip G. Griffin, Cadastral Surveyor, under Group # 1529, surveyed April/July 1990 (DCSO records Vol. 50 Page(s) 19148-49)

Angle Point No. 9 on the S. bdy. of sec. 33, monumented with an iron post, 1 in. diam., firmly set, projecting 6 ins. above ground, with brass cap erroneously mkd.

AP 7
S S 33
1924

from which the remains of bearing trees of no record
A rotted, sawed fir stump, 16 ins. diam., bears East, 2 lks. dist., with healed blaze.
A rotted, sawed fir stump, 16 ins. diam., bears S.32°E., 16 lks. dist., with healed blaze.
and new bearing trees
A cedar, 10 ins. diam., bears S. 39° E., 26 lks. dist., mkd. AP9 S33 BT.
A Douglas fir, 9 ins. diam., bears N. 24½° W., 7 lks. dist., mkd. AP9 BT.
From this point, Angle Point No. 10 bears S.0°11'30"W., 1.880 chs.