

PRIMARY CORNER DESCRIPTION Sec. Cor. for 14, 15, 22 and 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Dennis Hathorn, Deputy, under Contract #57 dated April 12, 1855 (DCSO records, Vol. 12 Page 5243)

Set post, cor. secs. 14, 15, 22 and 23, from which
A B.Oak 10" dia., bears S.27°E., 25 lks. dist.
A B.Oak 15" dia., bears N.19°E., 53 lks. dist.
A B.Oak 12" dia., bears S.30°W., 81 lks. dist.
A B.Oak 10" dia., bears N.43°W., 47 lks. dist.

Ben B. Irving, Co. Surveyor - Jim Byron; Ray Irving; Ray Fee
March/April 1954 - C.S. File 45/262

Found - 1" Bolt at corner and one original BT stump only,
left.
12" B.Oak S.30°W., 81 lks., some scribes visible.
Set a 1" Iron pipe with brass cap mkd: County Surveyors Office
T27S R7W 15|14
22|23

We blaze and scribed the following:
10" R.Fir N.85°E., 31.0 ft. "S14 CS BT".
10" R.Fir S.24°E., 33.3 ft. "S23 CS BT".
8" R.Fir N.42°W., 25.0 ft. "S15 CS BT".
10" R.Fir S.72°30'W., 46.6 ft. "S22 CS BT".

Doug. County Surveyors Office - Vernon Tracy; Jack Heritage;
V. Perron - Sept. 18, 1968 - C.S. File 54/23-28

Found - 1954 DCSO brass cap in place.
10" now 14" Fir, recently sawed down, N.85°E.,
31.0 ft., shows scar.
10" now 10" Fir sawed stump, S.24°E., 32.3 ft. (Rec.
33.3 ft.) "BT" scribe visible on unhealed
blaze.
8" now 13" Fir, now down, N.42°W., 25.0 ft. shows
scar.
10" now 10" Fir sawed stump, S.72°30'W., 46.6 ft.
scribe visible on unhealed blaze.
New BTs - 7" D.Fir N.30°E., 31.8 ft. mkd. T27S R7W S14 CS BT.
10" D.Fir N.62°W., 22.6 ft. mkd. T27S R7W S15 CS BT.
8" D.Fir S.32°W., 35.9 ft. mkd. T27S R7W S22 CS BT.
9" D.Fir S.11°E., 28.5 ft. mkd. T27S R7W S23 CS BT.
Corner lies on gentle westerly slope approx. 200 ft. west of
power line road.

Fd. BC 10/2019 - B Knapp - 2019-0042B