

TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Sec Cor for 30 & 31; & 25 & 36, T27-9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by William P. Heyden, Deputy Surveyor, under contract #656, dated May 21, 1896 - (DCS0 records Vol. 13 Page(s) 5287-88)

Set a Fir post 3 ft. long, 4" sq., 24" in the ground, for cor. to secs. 25, 30, 31 and 36, marked T27S S30 on NE.; R8W S31 on SE.; S36 on SW.; and R9W S25 on NW. faces, with 1 notch on S. and 5 notches on N. edges, from which
A Fir 36" dia., bears N.33°30'E., 32 lks. dist. mkd. T27S R8W S30 BT.
A Cedar 24" dia., bears N.20°W., 41 lks. dist. mkd. T27S R9W S25 BT.
A Cedar 16" dia., bears S.81°W., 27 lks. dist. mkd. T27S R9W S36 BT.
A Hemlock 7" dia., bears S.28°30'E., 42 lks. dist. mkd. T27S R8W S31 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - M. Godfrey; J. Fee, crew - July 18, 1957 - C.S. File 49/5-2

Found - Orig. BT, 36" Fir now 52", N.33°30'E., 21.1 ft. Found "BT" bark scribed and parts of other scribe marks.
Orig. 24" Cedar now 32", N.20°W., 27.1 ft. Shows old face, rotted, no scribing found.
Base of stump of 12" Hemlock, S.28°30'E., 27.7 ft. SW. orig. BT, not found, in roadway.

This corner was renewed about 45 years ago but not of record in DCS0. May be recorded in Coos County.

Found - I find 18" Cedar, open face, scribed T27S R8W S31 BT, bears S.80°E., 16.5 ft. I add scribing to this BT, "DCS BT".

Set Brass cap at cor. mkd: County Surveyors Office
25|30 T27S
Coos Co. 36|31 Douglas Co.
1957

New BTs- 32" Cedar N.20°W., 27.1 ft. scribed T27S R9W S25 DCS BT.
52" Cedar stump S.33°W., 52.8 ft. scribed T27S R9W S36 DCS BT.
Rescribed renewed Cedar, S.80°E., 16.5 ft. (as described above)
Rescribed 52" Fir, N.33½°E., 21.1 ft. "T27S R8W S30 DCS BT". Bark scribed.

(Cont. Next Page)

TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 30 & 31; & 25, 36 T27-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - James W Byron, and crew - June 19, 1963 - C.S. File 49/79-85

Found - Brass cap at corner.
Scribed Cedar stump, S.33°W., 52.8ft.
Scribed Cedar stump, N.20°W., 27.1 ft.
New BT - 11" Hemlock bears S.73°E., 131.8 ft. scribed S31
T27S R8W CS BT.

BLM resurvey by Jack W. Bowder, Cadastral Surveyor, under Group #903, surveyed March 1977 - (DCSO records Vol. 39 Page(s) 15711-12)

At the Sec. Cor., perpetuated and recorded by Byron in 1957, monumented with an iron post 2" dia., firmly set, projecting 6" above ground with brass cap mkd. in 1957, from which the remains of the original bearing trees
A sawed Fir stump 52" dia., bears N.33½°E., 32 lks. dist., no marks visible.
A sawed Cedar stump 32" dia., bears N.20°W., 41 lks. dist., with scribe marks T27S R9W S25 DCS BT visible on open blaze. This tree rescribed by Byron.
and a bearing tree mkd. by Byron
A sawed Cedar stump 52" dia., bears N.33°W., 80 lks. dist., with scribe marks T27S R9W S36 DCS BT visible on open blaze.
and new bearing trees:
A Fir 8" dia., bears N.3½°E., 15 lks. dist., mkd. T27S R8W S30 BT.
A Fir 8" dia., bears S.66¼°W., 68½ lks. dist. mkd. T27S R9W S36 BT.
A Fir 8" dia., bears N.49 3/4°W., 86 lks. dist., mkd. T27S R9W S25 BT.
No suitable tree available in sec. 31.

Fd. OK, Jan. 1997 by C. Mulkins - M 126-26

Coos County Surveyors Office - Michael Dado, Surveyor - Crew: Matthew Martin & Bill Hales - Filed 3/9/2015 (Rec'd March 2015, no renewal date given) - C.S. File 65/87-33

Found - 2½" brass cap on a 1" O.D. iron pipe, 0-9' tall, in good condition and solid in the ground, slight lean to the south. We set a cedar post 2' North and paint the top in blue.
continued next page

TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Sec Cor for 30 & 31; & 25 & 36, T27-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

30" R.Cedar tall stump, 7' tall, N.18°W., 28.42' to left side center. Stump has a chopped at healed blaze with no visible marks. There is an axe hole high with a BLM tag and a Coos Bay Lumber back tag in place. We chop a new "X" and paint the "X" and the face in blue. 0BT. Good Condition.

42" W.Cedar stump, S.35°W., 52.45' to heart center. Approx. 1/3 of the stump is gone find no visible marks. We paint "BT" in blue. 1957 Poor

20" D.Fir tall stump, 6' tall, S.70°W., 45.38' to right side center. We find a healed blaze and a BLM tag in place. We paint the face in blue. 1976 Poor

17" D.Fir tall stump, 6' tall, N.48°30'W., 56.54' to right side center. We find a healed blaze and a BLM tag in place. We paint the face in blue. 1976. Poor

26" D.Fir, N.6°30'E., 09.98' to left side center. We find a healed blaze and a BLM tag in place. We paint the face and a band around the tree in blue. 1976 Good

New - 15" D.Fir, S.63°E., 20.32' to a nail at right side center. We blaze and scribe "T27 R8 S31 BT". We paint the blaze, scribes and a band around the tree in blue and attach a new yellow tag (Coos County)

5" D.Fir, S.66°W., 21.37' to a nail at right side center. We blaze and scribe "BT" low and "X" high. We paint the blaze, scribes "X" and a band around the tree in blue and attach a yellow Coos County tag.

5" D.Fir, N.43°30'W., 30.60' to a nail at left side center. We blaze and scribe "BT" low and "X" high. We paint the blaze, scribes "X" and a band around the tree in blue and attach a yellow Coos County tag.