

TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 100300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19 & 30 only (West)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William P. Heyden, Deputy Surveyor, under contract #656, dated May 21, 1896 - (DCSO records Vol. 13 Page(s) 5288-89)

Set a Yew post 3 ft. long, 4" sq., 24" in the ground, for cor. of secs. 19, 24, 25 and 30, marked T27S S19 on NE.; R8W S30 on SE.; S25 on SW.; and R9W S24 on NW. faces, with 2 notches on S. and 4 notches on N. edges; from which
A Fir 24" dia. bears N.28°E., 16 lks. mkd. T27S R8W S19 BT
A Fir 24" dia. bears S.8°30'E. 56 lks. mkd T27S R8W S30 BT
A Fir 36" dia. bears S.33°W., 36 lks. mkd. T27S R9W S25 BT
A Fir 50" dia. bears N.14°W., 30 lks. mkd. T27S R9W S24 BT

GLO survey by Samuel W. Lackland, Deputy Surveyor, under Contract #660, surveyed June/Aug. 1897 - C.S. File 64/76-3

(Found corner as set by Heyden as described above.)
I efface the markings on the established cor. referring to secs.in R. 9 W.

Weyerhaeuser corner report, no surveyor's name or stamp, no date of visit - C.S. File 58/271-5

Per note on file:
"The attached corners were visited by Douglas Co. crews with insufficient evidence available for remonumenting the corners. Weyerhaeuser information was not based on "found" original evidence and the County crew disagreed with many of Weyerhaeuser's bearing and distance to their set monument." July 1983 V. Laugen - This information added to the corner report on 9/20/2001. DCSO
Pipe present at corner
60" Fir N.36°E., 19.7 ft.
42" Fir S.89°E., 41.8 ft.

Survey by Robert C. Adamek - For: Weyerhaeuser Co. - Nov. 1975 - C.S. File 58/76 and M 58-54

Found no evidence of the original corner or its accessories. Re-established the corner by the single proportion method. Set 3/4" Iron pipe, from which
60" D.Fir stump, bears N.73°E., 40.1 ft. scribed SW COR S19 RP.
32" D.Fir stump, bears S.45°E., 100.3 ft. scribed NW COR S30 RP.

continued next page

TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 100300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19 & 30 only (West)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM resurvey by Jack W. Bowder, Cadastral Surveyor, under Group #903, surveyed March 1976 - (DCSO records Vol. 39 Page(s) 15714)

Point for the cor. of secs. 19 and 30 only, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 27 S	T 27 S.
R 9 W	
S 24	S 19
	S 30
	R 8 W 1976

No suitable trees available within limits.

Set a 5 ft. steel fence post alongside iron post.

Corner is located on ridge, bears N.80°W. and S.80°E.

Tony Hostetter - For: Weyerhaeuser - June 2014 - C.S. File 65/86-8

Found - 1976 BLM brass cap as described DCSO Vol. 39, pg. 15714. From which:

1976 BLM brass cap, CC Sections 24 & 25 T27S R9W bears S.01°10'E, 101.32 ft.

New BTs- 12" fir, Scribed "S 19 SW BT", BT tag, bears N.15°16'E., 19.9 ft to spike.

14" fir, Scribed "S30 NW BT", BT tag, bears S.15°21'E., 12.4 ft to spike.

12" fir, Scribed "S 19 SW BT", BT tag, Bears N.88°02'W, 11.2 ft to spike.