

PRIMARY CORNER DESCRIPTION Sec. Cor. for 18 & 19 only (West)

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by William P. Heyden, Deputy Surveyor, under contract #656, dated May 21, 1896 - (DCSO records Vol. 13 Page(s) 5289-90)

Set Yew post 3 ft. long, 4" sq., 24" in the ground, for cor. of secs.13, 18, 19 and 24, marked T27S S18 on NE.; R8W S19 on SE.; S24 on SW.; and R9W S13 on NW. faces, with 3 notches on N. and S. edges, from which
A Hemlock 12" dia., bears N.57°30'E., 40 lks. dist. mkd. T27S R8W S18 BT.
A Hemlock 24" dia., bears S.22°E., 49 lks. dist. mkd. T27S R8W S19 BT.
A Hemlock 20" dia., bears S.60°W., 27 lks. dist. mkd. T27S R9W S24 BT.
A Fir 40" dia., bears N.18°15'W., 90 lks. dist. mkd. T27S R9W S13 BT.

GLO survey by Samuel W. Lackland, Deputy Surveyor, contract #660, dated May 31, 1896, surveyed June/Aug. 1897 - C.S. File 64/76-3

I destroy the markings on this cor. referring to secs. in R 9 W.

Weyerhaeuser corner report, no surveyor's name or stamp, no date of visit - C.S. File 58/271-5

Per note on file:
"The attached corners were visited by Douglas Co. crews with insufficient evidence available for remonumenting the corners. Weyerhaeuser information was not based on "found" original evidence and the County crew disagreed with many of Weyerhaeuser's bearing and distance to their set monument." July 1983 V. Laugen - This information added to the corner report on 9/20/2001. DCSO
Pipe present at corner
24" Fir stump N.49°E., 16.2 ft.
10" Hemlock N.89°E., 26.4 ft.
54" Fir N.14½°E., 25.7 ft.

Survey by Robert C. Adamek - For; Weyerhaeuser Co. - (Elk Wallow Survey) July 13, 1977 - C.S. File 58/139 & M 66-12

Set by single proportion. Chipped a notch into a rock face for the section corner. Referenced the cor. as follows:
12" D.Fir bears S.57°W., 17.3 ft. scribed STD CNT RP.
60" D.Fir snag, bears S.64°E., 14.8 ft. scribed STD CNR RP