

TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Standard Cor. for 32 & 33, (South)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by William P. Heyden, Deputy Surveyor, under contract #656, dated May 21, 1896 - (DCSO records Vol. 13 Page(s) 5281)

Set a Yew post 3 ft. long, 4" sq., 24" in the ground for standard cor. of secs. 32 and 33 marked S C T27S R8W on N.; S32 on W.; and S33 on E. faces, with 2 grooves on W. and 4 grooves on E. faces; from which
A Hemlock 12" dia., bears N.20°W., 50 lks. dist. mkd. T27S R8W S32 BT.
A Hemlock 9" dia., bears N.88°E., 40 lks. dist. mkd. T27S R8W S33 BT.
Elevation of this corner 200 ft. above Wilson Creek.

BLM Resurvey by C. Albert White; John M. Jelley; James E. Jelley, Cadastral Surveyors, Under group #466, Surveyed Sept/Oct. 1961 - (DCSO records Vol. 30 Page(s) 12869-70)

The standard cor. of secs. 32 and 33, determined at record bearing and distance from the remaining original bearing tree:
A dead Hemlock 10" dia., bears N.88°E., 40 lks. dist. mkd. S33 T27S R8W on open face.
At the corner point
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

	S	C	
T 27 S		R 8 W	
S 32		S 33	
1961			

from which new bearing trees:
A Hemlock 43" dia., bears N.31½°E., 120 lks. dist. mkd. T27S R8W S33 SC BT.
A Hemlock 26" dia., bears N.11°W., 32 lks. dist. mkd. T27S R8W S32 SC BT.
From this point a Bureau of Land Management approximate corner point, number 405, a 2" iron pipe, protruding 18" above ground, bears South 3 lks. dist.

Douglas Co. Surveyors Office - James W. Byron and crew - June 1963 - C.S. File 49/79-85

Found - Brass cap at corner. NE BT has been cut.
26" Hemlock N.11°W., 21.1 ft., OK, shows good scribing.
New BT - 36" Cedar bears N.2°E., 39.9 ft. scribed S33 T27S R8W CS BT.

(Cont. Next Page)

TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Standard cor. secs. 32 & 33, (South)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
May 14, 1970 - C.S. File 54/113-10

Found - 1961 Cadastral brass cap, was pushed over and buried. RESET brass cap at corner point.
36" Cedar, alive, N.2°E., 39.9 ft. scribe visible on unhealed blaze "T27SR8W S33 SC BT". We add "CS".
We add "CS"
All other BTs destroyed.
New BT - 7" Hemlock N.17°W., 31.4 ft. mkd. T27S R8W S32 SC CS BT.

This corner lies on top of cut bank of westerly side of the Burnt Mt. access road, approx. 60 ft. West of centerline.

Tony Hostetter - For: Weyerhaeuser - Feb. 2005 (added 7/31/2019) - M147-36

Found - 1961 BLM brass cap from which:
12" Cedar stump, BLM tag, scribing visible, bears N.02°E., 39.9 ft.
New BTs- 18" Fir, scribed "S33 SW BT", bears N.06°22'E., 0.8 ft. to spike.
16" Hemlock, scribed "S32 BT", bears S.10°W., 40.9 ft. to spike.
16" Fir, scribed "S32 SE BT", bears N.72°51'W., 19.0 ft to spike.