

PRIMARY CORNER DESCRIPTION Standard Cor. Secs. 33 & 34, (South)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William P. Heyden, Deputy Surveyor, under contract #656, dated May 21, 1896 - (DCSO records Vol. 13 Page(s) 5280)

-----  
A Cedar 7" dia., (same having been blazed on old line) for standard cor. to secs. 33 and 34, marked S C T27S R8W on N.; S34 on E.; and S33 on W.; sides with 3 grooves on E. and W. sides; from which

A Fir 16" dia., bears N.34°E., 57 lks. dist. mkd. T27S R8W S34 BT.

A Fir 14" dia., bears N.61°W., 40 lks. dist. mkd. T27S R8W S33 BT.

G. Robert Lecklider - For: Dale McFarland - Jan. 1961 - C.S. File 51/162

-----  
Found - Cedar stake at corner, down, badly decayed, scribe visible.

24" Fir N.34°E., 37.6 ft., cat face.

22" Fir N.61°W., 26.4 ft., cat face, badly burned.

Set steel tube with survey cap at corner.

Scribed- 22" Fir N.1°E., 28.2 ft.

25" Fir N.70°W., 31.4 ft.

Corner lays about 35 ft. North of E-W ridge in old growth Fir stand and falls about 100 ft. North of the North line of Sec. 4, T28S R8W.

BLM Resurvey by C. Albert White; John M. Jelley; James E. Jelley, Cadastral Surveyors, Under group #466, Surveyed Sept/Oct. 1961 - (DCSO records Vol. 30 Page(s) 12868)

-----  
The Sec. cor., perpetuated by Lecklider with a chromed iron pipe ¼" dia., protruding 18" above ground, in a mound of stone 2 ft. base to top, with cap mkd. Property Corner. A small portion of the original corner tree, mkd. with illegible scribe marks, was found lying beside the pipe; from which the original bearing trees:

A Fir 22" dia., bears N.36°E., 57 lks. dist. mkd. with a healed blaze, and BT on an opened face. (Rec. brg. N.34°E.)

A Fir 20" dia., bears N.61°W., 40 lks. dist. mkd. with a burned face.

and bearing trees mkd. by Lecklider:

A Fir 22" dia., bears N.2½°E., 43 lks. dist. mkd. T27S R8W S34 CC BT RE 4079, and Lecklider's cruiser mark.

A Fir 25" dia., bears N.71°W., 37 lks. dist., mkd. T27S R8W CC S33 BT RE 4079, and Lecklider's cruiser mark.

(Cont. Next Page)

TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Standard Sec. cor. 33 & 34, (South)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

At the corner point  
Set an iron post, 28" long, 2 1/2" dia., 22" in the ground,  
with brass cap mkd:

S C  
T 27 S | R 8 W  
S 33 | S 34  
-----  
1961

from which a new bearing tree  
A Hemlock 10" dia., bears N.29½°W., 16 lks. dist. mkd.  
T27S R8W S33 SC BT.  
Deposit Lecklider's iron pipe beside iron post.

Douglas Co. Surveyors Office - John M. Powell, and crew - May  
18, 1970 - C.S. File 54/113-17

-----  
Found - 1961 Cadastral brass cap, properly set & mkd. with  
Lecklider's pipe and cap alongside.  
Orig. 22" Fir, alive, N.36°E., 37.6 ft., tagged,  
chopped open and scribe visible.  
10" now 12" Hemlock, alive, N.29½°W., 10.6 ft.,  
scribe visible on partially healed blaze.  
All other BTs are turned out stumps.  
New BT - 10" Hemlock N.34°E., 23.6 ft. mkd. T27S R8W S34 SC  
CS BT.  
Corner lies 50 ft. West of top of ridge, course SW. & NE.

Weyerhaeuser corner report, no surveyor's name or stamp, no  
date of visit - C.S. File 58/271-14

-----  
Per note on file:

"The attached corners were visited by Douglas Co. crews  
with insufficient evidence available for remonumenting the  
corners. Weyerhaeuser information was not based on "found"  
original evidence and the County crew disagreed with many of  
Weyerhaeuser's bearing and distance to their set monument."  
July 1983 V. Laugen - This information added to the corner  
report on 2/6/2008. DCSO  
From pipe at corner point: 24" Fir N.38°E., 36.2 ft.  
8" Hemlock N.34°E., 23.6 ft.  
12" hemlock N.29¼°W., 12.7 ft.