

TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Cor. Secs. 26, 27, 34, & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William P. Heyden, Deputy Surveyor, under contract #656, dated May 21, 1896 - (DCSO records Vol. 13 Page(s) 5306-7)

-----  
Set a yew post, 3 ft. long, 4" sq., 24" in the ground, for cor. of secs. 26, 27, 34, & 35, 100 ft. below ridge, marked T27 S26 on NE, R8W S35 on SE, S34 on SW, and S27 on NW faces; with 1 notch on S and 2 notches on E edges; from which  
A Cedar, 15" dia. bears N.8°E. 54 lks. mkd:T27S R8W S26 BT  
A Fir, 30" dia. bears S.40°E. 117 lks. mkd:T27S R8W S35 BT  
A Fir, 20" dia. bears S.60°W. 32 lks. mkd: T27S R8W S34 BT  
A Fir, 30" dia. bears N.41°W. 42 lks. mkd: T27S R8W S27 BT

Weyerhaeuser corner report, no surveyor's name or stamp, no date of visit - C.S. File 58/271-11 (&14)

-----  
Per note on file:  
"The attached corners were visited by Douglas Co. crews with insufficient evidence available for remonumenting the corners. Weyerhaeuser information was not based on "found" original evidence and the County crew disagreed with many of Weyerhaeuser's bearing and distance to their set monument." July 1983 V. Laugen - This information added to the corner report on 9/21/2001. DCSO  
Pipe  
8" Hemlock, S.14°W., 6.4 ft.  
24" Cedar, N.8°E., 53.0 ft.  
36" Fir, N.70°E., 39.0 ft.  
Fir windfall S.40°E., 77.0 ft.

Douglas Co. Surveyors Office - Gregory E. Quibell, Deputy - John Powell - 5/6/1982 (typed 9/21/2001) - C.S. File 58/271-4

-----  
Condition report only  
Found - Unrecorded 1" I.P. protruding 16" out of ground.  
54" Fir stump with Weyerhaeuser BT tag bears N.70°E., 39.0 ft.  
24" Fir stump with Weyerhaeuser BT tag bears S.22°E., 13.0 ft.  
No trace of orig. BTs.