

PRIMARY CORNER DESCRIPTION Cor. Secs. 25, 26, 35, & 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 13 Page(s) 5296 and corrective survey June 1898 Page 5355)

Page 5296

Set a yew post, 3 ft. long, 4" sq., 24" in the ground for cor. to secs. 25, 26, 35, & 36, marked T27S S 25 on NE, R8W S 36 on SE, S 35 on SW, S 26 on NW faces, with 1 notch on S & E edges; from which

- A fir, 30" dia. bears N.26°E. 56 lks. mkd: T27S R8W S25 BT
- A fir, 10" dia. bears S.20°E. 68 lks. mkd: T27S R8W S36 BT
- A fir, 24" dia., bears S.56°30'E., 65 lks., mkd: T27S R8W S35 BT.
- A fir, 26" dia., bears N.35°W., 120 lks., mkd: T27S R8W S26 BT.

Page 5355

Intersect cor. to secs. 25, 26, 35, & 36, marked as described by the Examiner. I supply the omitted markings on post to-wit. T27S on NE, R8W on SE, with 1 notch on S & E edges. BTs as reported in orig. notes.

Douglas Co. Surveyors Office - John M. Powell - Willie Penley - J. Heritage - 4/13/1971 - C.S. File 54/119-8

Found - 24" D.Fir, now 36" stump, blow down, S.56°30'W., 42.9 ft., opened stump for scribe, "R8W"
Stump hole N.26°E., 37.0 ft., (edge of hole). No trace of stump.

No trace of any other BTs. Ring count places age of SW BT at 65 years. Tree down for sometime. Orig. survey 1986.

After good search, use hole of the SW BT to set corner.

Set - Brass cap at cor. mkd: COUNTY SURVEYORS T27S R8W
OFFICE 1971 S 26|S 25
S 35|S 36

New BTs- 7" W.Fir S.47°E., 18.0 ft scribed T27S R8W S36 CS BT
8" Cedar S.44°W., 19.7 ft scribed T27S R8W S35 CS BT
10" Hemlock N.83°W., 22.4 ft. scribed T27S R8W S26 CS BT.
13" Hemlock N.46°E., 61.8 ft. scribed T27S R8W S25 CS BT.

Note - This corner lies in partially logged area.

continued next page

TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Cor. Secs. 25, 26, 35, & 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas County Surveyors Office - Randall Smith & Stephen
Flause - May 19, 1997 - C.S. 64/74-34

Found - 2½" dia. Brass cap on a 1½" O.D. iron pipe,
protrudes 19" above ground.
10" now 14" dia. 1½' high broken hemlock stump, with
scribing visible on a partially healed blaze
"BT", bears N.81°W., 22.4' (rec. N.83°W., 22.4').
7" now 16" dia. W.Fir, with a fully healed double
blaze, bears S.49°E., 18' (rec. S.47°E., 18').
13" now 14" dia. 5½' high hemlock stump, with
scribing visible of an open blaze "T27S R8W S25
CS", bears N.44½°E., 61.8' (rec. N.46°E., 61.8').
The only remaining original BT is a 24" now down 36"
dia. D.Fir, with a previously opened blaze
illegible scribing found. Root hole agrees with
rec. "S.56½°W., 42.9'". OBT.
Set- BC/IP is surrounded by a 1½' dia. mound of stone.
10" dia. D.Fir double blazed and scribed "T27S R8W
S26 CS BT", bears N.74°W., 15.2'.
15" dia. D.Fir double blazed and scribed "T27S R8W
S25 CS BT", bears N.79½°E., 15.4'.

Fd. Ok by Tony Hostetter, 8/2002 - M140-72