

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 & 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 13 Page(s) 5299)

Set yew post, 3 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor., marked ¼ S on W face; from which
A fir, 36" dia., bears N.22°E., 48 lks., mkd: ¼ S BT.
A yew, 10" dia., bears N.26°W., 44 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - Gregory Quibell, Deputy - John Powell - May 1982 - C.S. File 61/36-5

Found - Orig. 36" fir, now 44" with two good scars plus numerous cruiser marks
Orig. 10" yew destroyed by cat trail.
Set - At record bearing and dist. (S.22°W., 31.7 ft.) from the orig. 36" now 44" fir BT, I SET a 1"x30" I.P. with brass cap attached stamped "Douglas County Surveyors Office T27S ¼ S23 S24 R8W 1982".
New BTs- 42" fir scribed "¼ S23 CS BT" in double blaze, bears S.34°W., 20.3 ft.
30" fir scribed "¼ S24 CS BT" in double blaze, bears S.52°E., 31.4 ft.
42" fir with "W" nail in face bears S.84°W., 11.7 ft. to nail.
Sketch of accessories in C.S. file.

Weyerhaeuser corner report, no surveyor's name or stamp, no date of visit - C.S. File 58/271-7

Per note on file:
"The attached corners were visited by Douglas Co. crews with insufficient evidence available for remonumenting the corners. Weyerhaeuser information was not based on "found" original evidence and the County crew disagreed with many of Weyerhaeuser's bearing and distance to their set monument."
July 1983 V. Laugen - DCSO
The following information is on Weyerhaeuser Co. paper:
(From Corner position): 48" Fir S.84½°W., 14.0 ft.
48" Fir N.22°E., 31.7 ft.