

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 25 & 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 13 Page(s) 5297)

Set fir post, 3 ft. long, 4" sq. set in stone mound 3 ft. base 1½ ft. high, on point of rocky ridge, 100 ft. below summit, for ¼ sec. cor. mkd ¼ S on N face; from which
A hemlock, 16" dia., bears N.78°W., 62 lks., mkd: ¼ S BT.
A fir, 28" dia., bears S.68°E., 19 lks., mkd: ¼ S BT.

Weyerhaeuser corner report, no surveyor's name or stamp, no date of visit - C.S. File 58/271-9

Per note on file:
"The attached corners were visited by Douglas Co. crews with insufficient evidence available for remonumenting the corners. Weyerhaeuser information was not based on "found" original evidence and the County crew disagreed with many of Weyerhaeuser's bearing and distance to their set monument."
July 1983 V. Laugen - DCSO
The following information is on Weyerhaeuser Co. paper:
From a 1/2" Copper pipe, 15" up.
6" Fir bears N.07½°W., 15.6 ft.
14" Cedar snag bears S.20°W., 9.1 ft.
60" Fir stump bears S.38°E., 14.6 ft.

Douglas Co. Surveyors Office - Randall Smith & Stephen Flause - May 14, 1997 C.S. 64/74-32

Found - None
48" dia. 2½' high D.Fir stump, with a W.T.CO. corner tag nailed on top no blazes visible, tag reads "14.7' N.38°W. to N¼ cor T27S R8W S36 JFE 8-21-72 NOO 7-11-52".
12" dia. D.Fir, with flagging protruding from a small healed blaze possible W Nail inside blaze. W.T.C.O. corner tag reads "15.6' S.07½°E., to S¼ T27S R8W S25".
(Note above trees mark an intersection)
14" dia. 12' high cedar snag, with axe marks W.T.C.O. tag reads "T27S R8W S36 N¼ HTH JFE 8-21-72 RJOH 8-72" this tree is approx south 8' from a calc. corner position determined from above trees.
Position of OBT'S fall at edge of cat road.
Note this corner not renewed in 1983 by DCSO see C.S. 58/271

continued next page

TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 640200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 25 & 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Tony Hostetter - For: Seneca Jones Timber Co. - Aug. 2002 - M140-72

Found - 3 BTs marked by Weyerhaeuser company (according to WEYCO records 2 original GLO BTs were found with visible scribing in 1952. The corner position was monumented with a ½"- alloy pipe at that time. Subsequent records indicate that the BTs present now reference the corner position as marked by the ½" pipe, which has evidently been removed by logging. No evidence of the original BTs remain).

Set - 5/8"x36" rebar w/2½" cap marked "S25 S36 ¼ LS1975 2002" from WEYCO BT information From which:

12" Fir, WEYCO tag, bears N.7½°W., 15.6 feet.

50" Fir stump WEYCO tag bears S.38°E. 14.6 ft to face

14" Cedar, WEYCO tag bears S.20°W., 9.1 feet.

New BTs- 10" Fir, scribed "S25 ¼ BT" bears N.52°E., 22.3 feet to spike.

14" Fir, scribed "S36 ¼ BT" bears: S.40°E., 8.9 ft to spike.