

TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 700240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 25 & Sec. 30; T27-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Dennis Hathorn, Under Contract #57 dated April 12, 1855 (DCSO records, Volume 12 Page 5227)  
-----  
Set ¼ sec. post, from which  
    A cedar, 12" dia., bears S.13½°E., 188 lks  
    A fir, 12" dia., bears S.35°W., 192 lks.

GL0 survey by A.R. Flint and L.C. Flint, under Contract #392, dated May 26, 1881 (DCSO records, Vol. 13 Pgs. 5265)  
-----  
Made cedar ¼ post, 3 ft. long, 3" sq. & set, from which the old witness trees bear.  
    A fir, 12" dia., bears S.35°W., 193 lks.  
    A cedar, 12" dia., bears S.13½°E., 188 lks.

Doug. County Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam - Jan 1960 (ADDED 5/25/2022) - C.S. File 49/79-40  
-----  
Found two scribed trees  
    Now 40" Cedar shows scribing on chip resting in old window. Also scribing ¼S in wood behind chip. This tree has been used for orig. cedar BT, by others. Faces OK but I do not believe it places cor. at orig. position, as we find old trees near, scribing may not be orig  
    We find now 30" Fir snag, we open and find scribing "S" probably scribed by Flint 1881 faces toward cedar BT. This scribing and face was partly destroyed by axe work, apparently soon after it was scribed. We find no scribing facing to NE. Also it puts the cor. near other larger & older trees.  
    I doubt if either BT is an orig. BT or the record dist. & bearings are N.G.  
    Sketch shows BTs: 30" Fir S.67½°W., 48.4' from 40" Cedar.  
-----  
Weyerhaeuser corner report, no surveyor's name or stamp, no date of visit - C.S. File 58/271-9  
-----  
(See above DCSO report added 5/25/2022, JC)  
Per note on file: "The attached corners were visited by Douglas Co. crews with insufficient evidence available for remonumenting the corners. Weyerhaeuser information was not based on "found" original evidence and the County crew disagreed with many of Weyerhaeuser's bearing and distance to their set monument." July 1983 V. Laugen - DCSO This information added to the corner report on 9/20/2001. DCSO  
The following information is on Weyerhaeuser Co. paper:  
Continued next page

TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 700240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 25 & Sec. 30; T27-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

From 3/4" pipe (up 10"):  
14" (15" windfall) fir N.42½°E., 19.2 ft.  
22" hemlock (windfall) S.31°W., 7.9 ft.  
Parenthesis info add to Wey-Co info probably by GQ DCS0, JC

Tony Hostetter - For: Weyerhaeuser Co. - July 2001 - M138-66  
-----

No evidence of orig. corner or accessories.  
Set - 5/8"x30" rebar w/plastic cap mkd: "LS 1975" at proportionate dist.  
24" W.Fir, scribed "S 30 ¼ BT" bears N.62°02'E., 49.1 ft. to spike. Measured to the head of 6" spike. BT tag.  
22" W.Fir, scribed "S 30 ¼ BT" bears S.84°34'E., 39.7 ft. to spike. Measured to the head of 6" spike. BT tag.  
8" Fir, scribed "S 25 ¼ BT" bears S.55°51'W., 10.7 ft. to spike. Measured to the head of 6" spike. BT tag.  
9" Fir, scribed "S 25 ¼ BT" bears N.9°58'W., 7.5 ft. to spike. Measured to the head of 6" spike. BT tag.  
3/4" iron pipe (not recorded) bears N.52°29'E., 36.74 ft. Note: There is a Cedar stump at approx. GL0 measurement from this pipe but no scribing or other evidence was found.