

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by William P. Heyden, Deputy Surveyor, under contract #656, dated May 21, 1896 - (DCSO records Vol. 13 Page(s) 5282)

Set a Yew post 3 ft. long, 4" sq., 24" in the ground, for standard ¼ sec. cor. marked S C ¼ S on N. face, from which
A Cedar 14" dia., bears N.40°E., 36 lks. dist. mkd. S C ¼ S BT.
A Cedar 40" dia., bears N.8°W., 33 lks. dist. mkd. S C ¼ S BT.

BLM Resurvey by C. Albert White; John M. Jelley; James E. Jelley, Cadastral Surveyors, Under group #466, Surveyed Sept/Oct. 1961 - (DCSO records Vol. 30 Page(s) 12870)

The standard ¼ sec. cor., determined at record distance from each of the original bearing trees:

A Cedar 14" dia., dead and down, bears N.43°E., 36 lks. dist., mkd. SC ¼ S on open blaze. (Rec. brg. N.40°E)
A Cedar 51" dia., bears N.3°W., 33 lks. dist. mkd. with a healed blaze and local cruiser marks. (Rec. brg. N.8°W.) Reblaze tree on the overgrowth and mark ¼ S32 SC BT.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

S C
T 27 S R 8 W
¼ S 32
1961

from which

A Hemlock 15" dia., bears N.68°E., 112 lks. dist. mkd. ¼ S32 SC BT with a Weyerhaeuser Timber Company spike, driven in a small blaze at the root crown.

From this point a Bureau of Land Management approx. corner point number 403, 2" Iron pipe protruding 30" above ground bears S.74°E., 2 lks. dist.

Douglas Co. Surveyors Office - R.B. Kimberling; S.J. Flause - Dec. 5, 1977 - C.S. File 59/42-20

Found - 2½" Iron pipe with brass cap set 2" above ground mkd. SC T27S R8W ¼ S32 1961.

51" Cedar stump uprooted, stump hole, bears N.3°W., (Rec. N.8°W.) 21.8 ft. with visible scribing "¼ S32 CS BT" in a partially healed double blaze.

New BTs- 38" Fir stump bears N.39°W., 37.1 ft. with a boat spike driven in center marked "BO 2"

(Cont. Next Page)

TOWNSHIP 27½ RANGE 08 POINT IDENTIFIER # 233200

PRIMARY CORNER DESCRIPTION Standard ¼ sec. cor. S.32, T27-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

42" Fir stump bears S.11½°W., 38.3 ft. with a boat spike driven in top marked "BO 1"
Corner is 30 ft. South of logging road at edge of temporary landing.

Tony Hostetter - For: Weyerhaeuser - Feb. 2005 (added 7/31/2019) - M147-36

Found - 1961 BLM brass cap from which:
42" Fir stump, BLM tag, spike in top, bears S.11°W., 38.3 ft.
38" Fir stump, described by DC Surveyor has been uprooted.
New BTs- 14" Fir, scribed "S32 ¼ BT", bears N.15°E., 10.2 to spike.
16" Fir, scribed "S32 ¼ BT", bears S.10°E., 11.9 ft. to spike.
BTs measured to 6" spikes placed in root collar below face.